EARTHQUAKE ENGINEERING RESEARCH CENTER

THE PERFORMANCE OF EARTH DAMS DURING EARTHQUAKES

by

H. Bolton Seed

Faiz I. Makdisi

Pedro De Alba

Report No. UCB/EERC-77/20

August 1977

A report on research sponsored by the National Science Foundation

> College of Engineering University of California

Berkeley, California

ĥ

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED FROM THE BEST COPY FURNISHED US BY THE SPONSORING AGENCY. ALTHOUGH IT IS RECOGNIZED THAT CERTAIN PORTIONS ARE ILLEGIBLE, IT IS BEING RELEASED IN THE INTEREST OF MAKING AVAILABLE AS MUCH INFORMATION AS POSSIBLE.

THE PERFORMANCE OF EARTH DAMS DURING EARTHQUAKES

by

H. Bolton Seed¹, Faiz I. Makdisi², and Pedro De Alba³

Introduction

The study of the behavior of dams and embankments under conditions of earthquake loading has been the subject of much study during the past decade. As a result major advances have been achieved in understanding the nature of soils under cyclic loading and in the development of analytical tools for the study of the dynamic response of embankments to earthquake loading. This progress has led to the development of dynamic analysis procedures for evaluating the stability of embankments during earthquakes.

It was not, however, until the near catastrophic failure of the Lower San Fernando Dam during the 1971 earthquake that the attention of regulatory agencies and the design profession was seriously directed towards reevaluating existing conventional design tools and attempting to adopt the more recently developed dynamic analysis procedures for evaluating seismic stability. Since then, many dams have been studied using dynamic analysis techniques.

It should be emphasized, however, that in any rational approach to the design of embankments against earthquakes, in addition to the proper use and understanding of the material properties and behavior during seismic loading, and in addition to the proper use of analytical procedures to

¹Professor of Civil Engineering, University of California, Berkeley, Calif.
²Project Engineer, Woodward-Clyde Consultants, San Francisco, Calif.
³Assistant Professor of Civil Engineering, University of New Hampshire.

ţ,

estimate the dynamic response, considerable insight and judgment are required; this can only be gained through an intimate knowledge of the strengths and limitations of the analysis and testing procedures themselves and by studying the behavior of similar embankments during actual earthquake loading conditions. Accordingly the purpose of the present paper is to summarize available information concerning the behavior of dams subjected to strong earthquake shaking. A similar survey was presented by Ambraseys (1960); the present paper is intended to complement this initial review by presenting further details concerning embankment construction materials and procedures and performance records in earthquakes during the past 17 years.

A review of information on embankment dam performance shows that most of the available data has resulted from studies of earth dam performance in 6 major earthquakes:

1. San Francisco earthquake of 1906.

2. The Ojika (Japan) earthquake of 1947.

3. The Fallon (Nevada) earthquake of 1954.

4. The Kern County (California) earthquake of 1952.

5. The Tokachi-Oki (Japan) earthquake of 1967.

and 6. The San Fernando (California) earthquake of 1971. However, useful information on individual embankments has occasionally resulted from other earthquakes. It is hoped that the salient features of observed embankment performance during these various events can be summarized in the following pages and appropriate conclusions drawn to aid the design engineer in making more meaningful evaluations of the data provided by analytical design procedures.

Performance of Embankment Dams in the 1906 San Francisco (California) Earthquake

At the time of the 1906 San Francisco earthquake, which resulted from rupture along some 270 miles of the San Andreas fault, a significant number of earth dams had already been constructed in California and were subjected to strong shaking during the earthquake. Surveys show that 33 dams, ranging in height from 15 to 140 ft were located within 37 miles of the fault; the relative locations of these dams and the fault are shown in Fig. 1.

For each of these dams, data were collected on the following features:

- (1) Date of construction.
- (2) Distance from the fault and the probable maximum acceleration in rock at the site.
- (3) Geometric configuration of the embankment, i.e., height, slopes and depth of foundation.
- (4) Method of construction (where available).
- (5) Types of soils comprising the embankment and foundation.
- (6) Extent of damage due to shaking.

A concise summary of this information is presented in Table 1. Estimates of the maximum accelerations developed in rock at the various dam sites were estimated on the basis of acceleration attenuation curves developed for the Western United States (Schnabel and Seed, 1972).

The close proximity of many of these dams to the fault on which this major earthquake occurred is emphasized by the data summary in Table 2. Here the dams are divided into four groups and it is readily apparent that almost half (16) were located within 5 miles of the causative fault of what many people consider to be one of the strongest earthquakes in the known history of the United States.



Fig. 1. LOCATIONS OF DAMS SHAKEN BY THE SAN FRANCISCO 1906 EARTHQUAKE.

DAMS WITHIN 35 MILES OF SAN ANDREAS FAULT - 1906 EARTHQUAKE. Table 1:

Name of loss Control for the control of the contro of the control of the control of the control of the control of t			Distance					Estimated
	Name of Dam	Constr.	rrom fault (miles)	Heig. (ft)	ht Embankment Material	Foundation Material	Performance During 1906 Earthquake	acceleration in Base Rock (g)
	1 San Andreas	1870	0	97	sandy clays & clayey sands	clays mixed with sand 6 gravel	minor long & transverse cracks	0.8
1 Control 101 0 3 Control 101 0 3 Control 0 0 Control 0 0 Control 0	² Upper Crystal Spring Old San Andreas b	<pre>1877 efore 1875 </pre>	00	75	probably similar to San Andreas	clays mixed with sand & gravel	minor long. cracks	8°0
4 lower (nower) 1971 0 3 constrained and forces 5 lower (nower) 57 0 5 lower (nower) 1890 1 3 5 6 analyse (ny, name (ny, nity and notice) 6 analyse reported 0 0 7 crocker 1890 1.1 3 3 1144 300 1.1 3	³ Upper Howell	1878	0	38	probably same as lower Howell		cracks and settlement	0.8
5Also factor181803G. enorly clay, itano (lay, itano (4 Lower Howell	1877	0	38	sandy clays, clayey sand, weathered sandstone	crushed sandstone & shale	5' breach due to escaping water	0.8
	⁵ Lake Ranch	1878	0	36	Gr. sandy clay, lean clay, silty sand	Weathered sandstone	No damage reported	0.8
$ \begin{array}{{ccccccccccccccccccccccccccccccccccc$	6 Burlingame	1876	7	24	sandy clay, gravelly clay	sandy clay	No damage reported	0.8
⁶ Description Active 105 1.4 57 Name Clay and Addre (1)	7 Crocker	1890	1.3	45	silty sandy clay	sandy clay	No damage reported	0.75
9 9. kilzectos 166 2 103 Silty Clay, acue clayay sand Clay alked with gravel 0 e damage reported 0.75 0 Netre hume 1 2 5 Silty Clay, andy clay Medicock 10 0 class reported 0.75 1 Barrol 190 1 2 Silty Clay, andy clay Medicock 10 0 class reported 0.75 1 Barrol 190 1 1 Sandy Clays Medicock 10 0 class reported 0.75 1 Barrol 190 1 1 Sandy Clays Medicock 10 0 class reported 0 class 1 Barrol 190 1 1 Sandy Clays Sandy Clays Medicock 0 class reported 0 class 1 Barrol 190 10 10 10 10 10 10 10 1 Barrol 100 10 10 10 10 10 10 10 1 Barrol 100 10 10 10 10 10 10 1 Barrol 100 10 10 10 10 10	⁸ Emerald Lake #1	1885	1.4	57	Mixed Clay and Adobe		No damage reported	0.75
10 Netter Dume 2 30 Sitty Clay, andy clay Bedrock 60 60 0.5 11 Bast Guich 196 2 45 Sitty Clay, andy clay Menthered mala is no damage reported 0.5 12 Jaquuita 190 2 43 Sitty Clay and analy clay Menthered mala is no damage reported 0.5 13 Balvelere 190 5 13 Sandy Clay and clay and clay 0.60 14 Intr. Nourt N. Basin 1995 5 13 Sitty Sand, clayey sand, cr. Sandy Clays 0.60 15 Balvelere 190 12 5 40 Crayey sand, cr. Sandy Claye 0.60 15 Balvelere 190 12 5 40 Crayey sand, cr. Sandy Claye 0.60 15 Balvelere 190 12 5 40 Crayey sand, cr. Sandy Claye 0.60 15 Balvelere 190 19 12 Sandy Claye Sandy Claye 0.60 15 Balvelere 100 12 5 Sandy Claye Sandy Claye 0.60 16 Consell 12 Sandy Claye Sandy Claye Sandy Claye 0.60	9 Pilarcitos	1866	2	103	Silty Clay, some clayey sand	Clay mixed with gravel	No damage reported	0.75
11 Baser Gulch 196 2 45 Sity Clay and analy clay wathered shale a 10 damage reported 0.75 12 Jaqunita 1300 4 13 Sandy Clays Sandy Clays Sandy Clays Sandy Clays 0.60 13 Balvadere 1905 5 17 Sity Sandy Clay Sandy Clays Mander reported 0.56 13 Balvadere 1905 5 17 Sity Sandy Clay Sandy CLay, sity 10 0.60 14 Putv. Nourt N. Basin 1905 5 17 Sity Sandy Clay Sandy CL, Lay, sity 0.60 15 Faqunitas 1872 5 48 Sandy Clay Sandy CLay 0.40 0.60 15 Faqunitas 1872 19 19 19 19 10 0.60 16 172 5 48 Sandy Clay Sandy Clay Sandy Clay 0.60 17 Extent 190 19 19 19 10 10 0.60 18 Fadmit 190 19 19 11 Sandy Clay Sandy Clay visut 0.60 17 Extent 19 19 19 19 19 <	10 Notre Dame		2	50	Silty Clay, sandy clay	Bedrock	No damage reported	0.75
12Largentiet190415Sandy Clayssundattons andsandattons andsandattons andsandattons and (12) 13Berronter10554Greenity sandy clay (12)	11 Bear Gulch	1896	2	45	Silty Clay and sandy clay	Weathered shale &	No damage reported	0.75
13 Belvederer 190 5 48 Grevelly andy clay 14 0.60 0.60 14 Univ. Nourt N. Basin 1805 5 17 Sily Sandy clay, eand, cr. Sandy Gr. clay, silty No damage reported 0.60 15 Lequnitas 1871 5 48 Sandy clay, er. sandy vland- Suity sond, clayy sand, cr. clay No damage reported 0.60 15 Lequnitas 1871 5 48 Sandy clay, occasional sand wn Suity cr. clay No damage reported 0.60 17 Extense 1901 19 23 Sily to clayy sand vland- Suity cr. clay No damage reported 0.50 18 Piedmont 1905 18 23 Sily to clayy file and w/ Sandy Clay, occasional sand and Sandy Clay, socasional sand and No damage reported 0.50 18 Piedmont 1905 18 21 Sandy Clay, socasional sand and Nort clay suff) No damage reported 0.55 19 Piedmont 1905 18 21 Sandy Clay, socasional sand and Nort clay suff) No clay suff)	12 Lagunita	1900	4	15	Sandy Clays	sandstone Sandy clays and silty sand	No damage reported	0.65
14 Univ. Nourt N. Basin 183 5 17 Slity Sandy Clay Sandy Clay Sandy Clay 0.60 15 Lequnitas 1872 5 48 Sandy Clay Stiff sandy Clay No damage reported 0.60 15 Lequnitas 1872 5 48 Sandy Clay Stiff sandy Clay No damage reported 0.60 16 Cowell 190 12 50 Sandy Clay Stiff sandy Clay No damage reported 0.60 17 States 1901 18 93 Sandy Clay, constant Stiff sandy clay visate No damage reported 0.65 18 Feddmort 1903 18 93 Sandy Clay, constant Stiff sandy clay visate 0.13 18 Feddmort 1905 18 23 Stily sand Norty stiff) No damage reported 0.55 18 Feddmort 1905 18 0 Stiff slip Clays constant Nort figametric 0.35 19 1905 18 100 18 Nort crasks settlement 0.35 19 1905 18 100 190 190 100 100 19 190 190 190 190 <t< td=""><td>13 Belvedere</td><td>1905</td><td>ŝ</td><td>48</td><td>Gravelly sandy clay</td><td></td><td>No damage reported</td><td>0.60</td></t<>	13 Belvedere	1905	ŝ	48	Gravelly sandy clay		No damage reported	0.60
15 Lagunitas 1872 5 40 Sandy Ciay, gr. Sandy Ciay Sandy Gr. Jay No damage reported 0.60 16 Cowell 1390 12 5 Sandy Ciay, ciayey sand wand. Suff sandy ciay wand. No damage reported 0.60 17 Extates 1900 12 5 Sandy Ciay, ciayey sand wand. Suff sandy ciay for ciayes 0.45 18 19 19 19 3 Sandy Ciay, cocasional sand and stragments No damage reported 0.45 18 1905 18 2 Silty to ciayey sand war, suff. No damage reported 0.35 19 Piedmont 1905 18 40 Silty to ciayer sand war, suff. No 0.35 19 19 19 19 19 Silty to ciayer sand war, suff. No 0.35 19 1905 18 10 Silty to ciayer sand war, suff. No 0.35 19 Extrament 1905 18 No Silty ciayer sand war, suff. 0.35 19 Iake Temescal 1960 19 19 19 19 0.35 19 195 19 19 19 19 19 0.35 10 Silty tanda Nore ciayer sand w	14 Univ. Mount N. Basin	1885	ŝ	17	Silty Sand, clayey sand, Gr. sandv clav	Sandy Gr. Clay, silty sand	No damage reported	0.60
16 Covell 190 12 50 analy city or city or city of and Vand- stone fragments Stiff survey (lay v/sand- stone fragments Not city or city or city or city and Vand- stone fragments Not city or city or city or city and Vand- stone fragments 0.35 17 Brtthes 1903 18 93 Sandy City or city or city or city or city and store fragments 0.35 18 Piedmont 1903 18 23 Sandy City or city or city or city or city or city or store fragments 0.35 19 Betryman 1905 18 40 Silty to sandy city or city or city or city or city or city or store fragments 0.35 20 Lake Temescal 1969 18 105 Sandy City or city or city or city or city or store fragments 0.35 20 Lake Temescal 1969 18 105 Sandy City or store fragments 0.35 21 Labot 1991 19 105 Sandy City or store fragments 0.35 21 Labot 1992 19 105 Sandy City or store fragments 0.35 22 Sandy City or store fragments Sciff silty city or store fragments Not cracks 0.35 23 Sandy City or store fragments Sciff silty city or store fragments 0.35 24 Pacific Grove <t< td=""><td>15 Lagunitas</td><td>1872</td><td>ſ</td><td>48</td><td>Carden of an ender of an ender</td><td>Candin fre all act</td><td>No damage reported</td><td>0.60</td></t<>	15 Lagunitas	1872	ſ	48	Carden of an ender of an ender	Candin fre all act	No damage reported	0.60
17Batates19011893Sandy Clay. occasional sand and sand (very stift)O damage reported0.351852Silty to Clayey fine sand w/ andstone fragmentsSandy Clays Clayey Sand (very stift)Minor cracks & settlement0.3519Beryman19051852Silty to Clayey fine sand w/ stift silty clays w/gravelNinor cracks & settlement0.3519Beryman19051840Silty to casionalStiff silty clays w/gravel0.3520Lake Temescal190518105Sandy Clays and vlaysStiff silty clays w/gravel0.3521chabot199219135Sandy Clays and vlavelBedrockNinor cracks0.3521chabot199219135Sandy Clays and vlavelStiff silty clays w/gravel0.3522chabot199219135Sandy vlavelStiff silty clays w/gravel0.3523chabot199219135Sandy vlavelStiff silty sindy clay (sliff)No damage reported0.3524Fortest Lake19922921Sandy vlavelStiff silty sindy clay (sliff)No damage reported0.3525Semit19922913Stiff clay w/gravelStiff silty sindy clay (sliff)No damage reported0.3525Semit19922913Stiff clay w/gravelStiff silty sindy clay (sliff)No damage reported0.3526Forte199229 </td <td>16 Cowell</td> <td>1890</td> <td>12</td> <td>202</td> <td>sandy clay, yr. sawy clay Sandy Clay to clayey sand w/sand- stone fragments</td> <td>study dr. cray Stiff sandy clay w/sand- stone fracments</td> <td>No damage reported</td> <td>0.45</td>	16 Cowell	1890	12	202	sandy clay, yr. sawy clay Sandy Clay to clayey sand w/sand- stone fragments	study dr. cray Stiff sandy clay w/sand- stone fracments	No damage reported	0.45
18Piedmont19051852Silty to Clayey fine and W/ sundstone fragmentsSandy Claye Scilayey SandMinor cracks & settlement0.3519Berryman19051840Silty to sandy clays, occasionalStiff silty clays w/gravelNinor cracks & settlement0.3520Lake Temescal190518105Sandy Clay, iean clay, shale andBedrockMinor cracks & settlement0.3521Lake Temescal189219135Sandy Clay, sand store fragments0.350.3521Chabot18911921Sandy clay, sand store fragments0.350.3522Samity sand slity clay, stiff clay w/gravelStiff silty Sandy clay & bedrockNo damage reported0.3523Lake Ralphine189226200.350.3524Pacific Grove18922845Clayey soil0.3525Samity slity clay, stiff clay w/gravelSilty Sandy clay & bedrockNo damage reported0.3524Pacific Grove18922845Clayey soil0.3525Samity slity clay, shale andNo damage reported0.350.3526189229Silty slity clay with clay with clay slity clay is bedrockNo damage reported0.2527Lake Ralphine189229Silty slity clay, slith0.3525Silty clay, s	17 Estates	1903	18	63	Sandy Clay, occasional sand and gravel	Sandy clay & Clayey sand [verv stiff]	No damage reported	0.35
19Bertyman19051840Silty sands0.3520Lake Temescal186918105Silty sands0.3521Lake Temescal186918105Sindy Clay, iaan clay, shale and sands clays and wyravelBedrockMinor cracks0.3521Chabor189219135Sandy Clay, iaan clay, shale and sands clays and wyravelBedrockNo damage reported0.3521Chabor189219135Sandy Clays and Clayey sand wyravelSilty Sandy clay (stiff)No damage reported0.3522Summit189223Sandy silty clay, stiff clay wyrock fragmentsNo damage reported0.3523Lake Ralphine18922620Clayery soil0.3524Pacific Grove18922860Clayery soil0.3525Ported18922950Silty clay, lean clay w/traces ofSilty gravelly clay0.3526Clayery soil18702950Silty clay, lean clay w/traces ofSilty gravelly clay0.25(0.5)*28Lake Herman19003250Silty gravelly clayNo damage reported0.2527Lake Herman190229Silty clay, gravelly clay, gravelly clayNo damage reported0.2528Iake Herman190229Silty clay, gravelly clay, gravelly clayNo damage reported0.2528Iake Herman190229Silty gravelly clay, gravelly clay </td <td>18 Piedmont</td> <td>1905</td> <td>18</td> <td>52</td> <td>Silty to Clayey fine sand w/ sandstone fragments</td> <td>Sandy Clay & Clayey Sand (verv stiff)</td> <td>Minor cracks & settlement</td> <td>0.35</td>	18 Piedmont	1905	18	52	Silty to Clayey fine sand w/ sandstone fragments	Sandy Clay & Clayey Sand (verv stiff)	Minor cracks & settlement	0.35
20Lake Temescal186918105Sandy Clay, iean clay, shale and sandstone fragmentsBedrockMinor cracks0.3521Chabot1991921sandstone fragmentsedanoge reported0.3522Summit19911921sandy sity clay, siff clay w/gravelGr. Sandy clay is bedrockNo damage reported0.3523Summit19911921sandy sity clay, siff clay w/gravelSilty sandy clay (siff)No0.3523Lake Ralphine18822235Yellowish brown clay w/rock fragmentsNo damage reported0.3524Racific Grove18822235Yellowish brown clay w/rock fragmentsNo damage reported0.3525Summit18922860Clayer soilNo damage reported0.250.3525Carayer soil18702950Silty gravelly clayNo damage reported0.2524Fertoren18702950Clayer soilNo damage reported0.2525Lake Herman19053250Clayer soilNo damage reported0.2529Lower St. Helena19053250Clayer soilNo damage reported0.2529Lower St. Helena19003250Clayer soilNo damage reported0.2529Lower St. Helena19003250Clayer soilNo damage reported0.2529Lower St. Helena1900 <td>19 Berryman</td> <td>1905</td> <td>18</td> <td>40</td> <td>Silty to sandy clays, occasional silty sands</td> <td>Stiff silty clays w/gravel</td> <td>No damage reported</td> <td>0.35</td>	19 Berryman	1905	18	40	Silty to sandy clays, occasional silty sands	Stiff silty clays w/gravel	No damage reported	0.35
21Chabot189219135sandscone fragments22Summit189219135sandy Clayey and Wyravel Gr. Sandy clay & bedrockNo damage reported0.3523Lake Ralphine18822235Yellowish brown clay w/pravel Gr. Sandy clay (stiff)No damage reported0.3524Facific Grove18822635Yellowish brown clay w/rock fragmentsNo damage reported0.3525Parcific Grove1882262037Yellowish brown clay w/rock fragmentsNo damage reported0.3525Port Costa18922845Clayey soilNo damage reported0.25(0.5)*26Fort St. Lake18922860Clayey soilNo damage reported0.25(0.5)*27Lake Chabot18702950Silty gravelly clayNo damage reported0.25(0.4)*28Eake Herman19053250Clayey soilNo damage reported0.25(0.4)*29Lower St. Helena19053250Clayey soilNo damage reported0.25(0.4)*29Lower St. Helena19003250Clayey soil <t< td=""><td>20 Lake Temescal</td><td>1869</td><td>18</td><td>105</td><td>Sandy Clay, lean clay, shale and</td><td>Bedrock</td><td>Minor cracks</td><td>0.35</td></t<>	20 Lake Temescal	1869	18	105	Sandy Clay, lean clay, shale and	Bedrock	Minor cracks	0.35
22 Summit 19 21 Sandy sity (any stiff clay wygravel or: sandy clay (stiff of od anage reported 0.35 23 Lake Ralphine 1892 22 35 Yellowish brown clay w/rock fragments 0.035 0.35 24 Ralphine 1882 22 35 Yellowish brown clay w/rock fragments 0.0 0.35 25 Partific Grove 1882 26 20 0.34 0.35 25 Part Costa 1892 26 Clayey soil 0.35 0.35 26 Fort Costa 1892 28 60 Clayey soil 0.25 0.35 26 Fort Costa 1892 28 60 Clayey soil 0.25 0.25 0.25 27 Lake Chabot 1870 29 50 Silty gravel 0.04 0.25	21 Chabot	1892	19	135	Sandstone fragments	daarda oo ta oo ta ahaa ahaa	tic democe recorded	0.35
23 Lake Ralphine 1882 22 35 Yeilowish brown clay w/rock fragments No damage reported 0.35 24 Pacific Grove 1882 26 20 0.13 0.35 25 Pacific Grove 1882 26 20 0.13 0.35 25 Pacific Grove 1882 26 0.14 volution 0.25 0.35 26 Fort Costa 1892 28 60 Clayey soil 0.25 0.25 0.25 27 Lake Chabot 1870 29 50 Slity clay, lean clay w/traces of slity gravelly clay No damage reported 0.25 <td< td=""><td>22 Summit</td><td>1681</td><td>19</td><td>21</td><td>Sandy silty clay, stiff clay w/gravel</td><td>GE: Sandy Clay & Deulock Silty Sandy clay (stiff)</td><td>No damage reported</td><td>0.35</td></td<>	22 Summit	1681	19	21	Sandy silty clay, stiff clay w/gravel	GE: Sandy Clay & Deulock Silty Sandy clay (stiff)	No damage reported	0.35
²⁴ Factific Grove 1882 26 20 ²⁵ Pactific Grove 1882 26 0.3 ²⁵ Fort Costa 1890 28 65 1344 soil 0.25(0.5)* ²⁶ Fort Costa 1890 28 66 Clayey soil 0.25(0.5)* 0.25(0.5)* ²⁶ Fort Costa 1890 29 50 Silty clay, lean clay w/traces of silty gravelly clay 0.04 amage reported 0.25(0.4)* ²⁷ Lake Chabot 1870 29 50 Silty clay, lean clay w/traces of silty gravelly clay No damage reported 0.25(0.4)* ²⁸ Lake Herman 1905 32 50 Clayey soil 0.25 0.25 ²⁹ Lower St. Helena 1900 32 50 Clayey soil 0.25 0.25 ²⁰ Upper St. Helena 1900 32 50 Lean clay, gr. sandy clay, gr. No damage reported 0.25 ³¹ Lake Camille 1800 33 100 33 10 0.25(0.5)* ³¹ Lake Erey 1894 37 83 Clayey soil No damage reported 0.25(0.5)* ³¹ Lake Camille 180	23 Lake Ralphine	1882	22	35	Yellowish brown clay w/rock fragments		No damage reported	0.35
26 Clayey soil No damage reported 0.25(0.5)* 27 Lake 1892 28 60 Clayey soil 0.25 27 Lake Chabot 1870 29 50 Silty clay, Hean clay w/traces of Silty gravelly clay 0.25 0.25 28 60 Clayey soil 0.25(0.4)* 0.25(0.4)* 0.25(0.4)* 28 Lake Herman 1905 32 50 Silty ventol 0.25(0.4)* 0.25(0.4)* 28 Lake Herman 1905 32 50 Clayey soil 0.25(0.4)* 0.25(0.4)* 29 Lake Herman 1905 32 50 Clayey soil 0.25(0.4)* 0.25(0.4)* 30 Upper St. Helena 1900 32 50 Clayey soil 0.25 0.25 31 Lake Camille 1800 33 30 Clayey soil 0.25(0.5)* 31 Lake Frey 1894 37 83 Gamage reported 0.25(0.5)* 31 Lake Frey 1894	25 port corts	1882	26	ខ្លះ			No damage reported	. 0.3
27 Lake Chabot 1870 29 50 UTRY clay, lean clay w/traces of silty gravelly clay No damage reported 0.25(0.4)* 28 Lake Herman 1905 32 50 clayey soil Clayey soil 0.25 28 Lake Herman 1905 32 50 clayey soil Clayey soil 0.25 29 Lake Herman 1905 32 50 clayey soil 0.25 30 Upper St. Helena 1900 32 50 Lean clay, gr. sandy clay, gr. 0.25 31 Lake Camille 1800 33 30 Clayey soil 0.25 31 Lake Frey 1894 37 83 Lean clay, gr. sandy clay, gr. 0.25(0.5)*	26 Forest Lake	1892	28	t č	Clayey soil rister soil		No damage reported	0.25
28Lake Herman19053250Clayey soilClayey AlluriumNo damage reported0.2529Lower St. Helena10783250Clayey soil0.2530Upper St. Helena19003250Lean clay, gr. sandy clay, gr.0.2531Lake Camile19003330Clayey soil0.2532Lake Camile18003330Clayey soil0.2532Lake Camile1800332Lake Camile0.2532Lake Frey1330Clayey soilNo damage reported0.25(0.5)*32Lake Frey19943783Lean clayBedrock0.20	27 Lake Chabot	1870	29	50	Silty clay, lean clay w/traces of	Silty gravelly clay	No damage reported	0.25(0.4)*
29 Lower St. Helena 1878 32 50 crayer solt 0.25 30 Upper St. Helena 1900 32 50 Lean clay, gr. sandy clay, gr. 0.4 amage reported 0.25 31 Lake Camille 1800 33 30 clayey soil 0.25 31 Lake Camille 1800 33 Lean clay gr. No damage reported 0.25 32 Lake Frey 1894 37 83 Lean clay Bedrock No damage reported 0.25(0.5)*	28 Lake Herman	1 9/15	32	50	sand & gravel			0 JE
³⁰ Upper St. Helena 1900 32 50 Lean clay, gr. sandy clay, gr. cl. sand 31 Lake Camille 1800 33 30 Clayey soil 32 Lake Frey 1894 37 83 Lean clay Bedrock No damage reported 0.25(0.5)*	29 Lower St. Helena	1878	32	2 2	TIDE JACK	CLAYEY ALLURIUM	No damage reported No damage reported	0.25
31 Lake Camille 1800 33 30 Clayey soil 32 Lake Frey 1894 37 83 Lean clay	30 Upper St. Helena	1900	32	50	Lean clay, gr. sandy clay, gr. cl sand		No damage reported	0.25
³² Lake Frey 1894 37 83 Lean clay Bedrock No damage reported 0.20	31 Lake Camille	1800	33	30	Clayey soil		No damage reported	0.25(0.5)*
	32 Lake Frey	1894	37	83	Lean clay	Bedrock	No damage reported	0.20

5

.

For an earthquake of magnitude about 8-1/4, it is estimated that these dams experienced base accelerations in rock of more than 0.6g at predominant periods of the order of 0.4 seconds, and durations of significant shaking of about 60 seconds. Considering the severity of such levels of shaking, and the fact that the natural periods of the embankments in question (median height 60') are not very different from the predominant period of the ground motion, one might expect substantial damage to have occurred. Yet the majority of the embankments survived the shaking without any significant damage at all. This behavior is in marked contrast to the behavior of the Upper and Lower San Fernando Dams in the earthquake of 1971, the behavior of a number of Japanese dams in the Tokachi-Oki earthquake of 1968 and the behavior of the Sheffield Dam in the Santa Barbara, California, earthquake of 1925. It is of interest, therefore, to explore the possible reasons for the excellent performance record in the San Francisco earthquake.

Three major factors are considered to contribute to the stability and performance of an embankment during an earthquake:

1) Section geometry (Upstream and downstream slopes),

2) Construction method and compaction procedure,

3) Type of embankment and foundation material.

Thus the data available on the 33 dams considered should be examined in the light of the above factors to determine if one or more of them was common to most embankments and might therefore serve to explain their excellent performance.

(1) Section Geometry:

Table 3 shows values of upstream and downstream slopes for 26 of the 33 embankments studied. Values of upstream slopes ranged between 1.3:1 and 3-1/2:1 and those for downstream slopes ranged between 1.3:1 and 3:1.

Distance from Fault	No. of Dams	Estimated Max. Accn. in Rock
- miles		- g
0 - 1	6	0.75 to 0.8
1, - 5	10	0.6 to 0.75
12 - 20	7	0,35 to 0,45
20 - 37	10	0.25 to 0.35

Table 3: EMBANKMENT SLOPES FOR DAMS AFFECTED BY 1906 EARTHQUAKE

Name of Dam	Upstream Slope	Downstream Slope
		· · · · · · · · · · · · · · · · · · ·
San Andreas	3-1/2:1	3:1
Upper Crystal Springs	2:1 & 3-1/4:1	2:1(75) 3-1/2:1
Old San Andreas		
Lake Ranch	2-3/4:1	2-1/2:1
Lower Howell	2:1	1-1/2:1
Upper Howell	2:1	2:1
Burlingame	2-1/2:1	2:1
Crocker	2-1/2:1	2:1
Emerald Lake #1	1.3:1	1,3:1
Pilarcitos	2-1/2:1	2:1
Notre Dame		
Bear Gulch	3:1	2.9:1
Lagunita	3:1	2:1
Belvedere	3:1	2:1
Univ. Mound N. Basin	3:1 & 1-1/2:1	2:1
Lagunitas	2-1/2:1	2:1
Cowell		
Estates	2:1	2:1
Piedmont	2:1	2:1
Berryman		3:1
Lake Temescal	1-1/2:1 & 3:1	2:1
Chabot	2:1	3:1 (with berm)
Summit	2:1	2:1
Lake Ralphine		
Pacific Grove	2-1/2:1	2:1
Port Costa		
Forest Lake	3:1	2:1
Lake Chabot	3:1	2:1
Lake Herman	3:1	2:1
Lower St. Helena	2:1	2:1 (berm) 2:1
Upper St. Helena	2:1	1-1/2:1
Lake Camille		
Lake Frey	2.7:1	2:1

Table 4: EXTENT OF DAMAGE, 1906 SAN FRANCISCO EARTHQUAKE

Est. Max, Accn.

Dai	m	Height	in Rock	Damage
San Andreas	-	97	0.8g	Minor long and transverse cracks
Upper Crystal	Springs	75	0.8g	Minor longitudinal cracks
Lower Howell		38	0.8g	5 ft breach due to ruptured outlet pipe
Upper Howell		38	0.8g	Some cracks and settlement
Piedmont		52	0,35g	Minor cracks and settlement

From an examination of Table 3 and from a comparison of the locations of the various embankments (the intensity of shaking they experienced and the resulting damage) and their corresponding slopes, there does not appear to be any correlation between the slopes of the embankments and their stability or performance during the earthquake. While the San Andreas Dam with slopes of 3 and 3-1/2:1, which was almost intercepted by the fault, suffered minor cracking, Pilarcitos Dam with similar height, construction procedure, foundation characteristics, and within 1.7 miles of the fault, but with slopes of 2-1/2 and 2:1 escaped without any damage.

Another example is Emerald Lake Dam with slopes of 1.3:1 and located within 1.5 miles of the fault, which escaped with no damage, in contrast to Piedmont Dam which is of similar height, at a distance of 18 miles from the fault, but with slopes of 2:1, and which suffered some cracking and crest settlement.

(2) Construction Procedure:

Unfortunately, not enough information is available on the construction procedures employed for the dams studied to permit a detailed comparative study of the effects of this factor; however, data are available on 12 dams and may be broken down as follows:

2 dams were compacted in 10" layers using 3-ton rollers

3 dams were compacted by teams and wagons

5 dams were compacted by moving livestock

2 dams were probably rolled in layers

From the information above and on the basis of the standard practice for that period, the general method of construction for these dams could be described as:

- placing the material in layers (various thicknesses have been used);
- using some means of compaction, either the hauling equipment, or moving live-stock, and at times light-weight rollers;
- water was used sometimes for wetting the soil, but moisture control methods did not exist at the time.

It seems unlikely, in view of modern construction techniques, that such methods would consistently result in dense compact material; accordingly the construction procedure does not serve to explain the excellent performance of the dams under the severe loading conditions to which they were subjected.

(3) Embankment and Foundation Material:

Table 1 provides a description of embankment material for the 33 dams considered. Most of the embankments consisted of clays of low to medium plasticity, while a few contained in addition some clayey sands.

The embankments were divided into three groups according to the type of soil of which they were constructed. Table 5 shows the dams forming the three groups and a definition of the type of soil in each group.

It may be seen from Table 5 that 31 of the 33 embankments consist of predominantly clayey soils or of mixed sandy clays and clayey sands, with only 2 being comprised partly of sandy soils.

A similar grouping was made for the foundation materials of the dams as shown in Table 6. In this case it was found that all of the embankments were underlain by bedrock, clayey soils, or very dense sand foundations.

(4) Overall Assessment of Performance:

Out of the 33 dams shaken by the earthquake, only 5 of the embankments were reported to have experienced any form of damage. Table 4 summarizes

Table 5: CLASSIFICATION OF DAMS ACCORDING TO TYPE OF EMBANKMENT MATERIAL

Predominantly Clay ¹	Mixed Clays to Clayey Sands ²	Predominantly Sands ³
Lake Ranch	San Andreas	Univ. Mound N. Basin*
Burlingame	Upper Crystal Springs	Piedmont**
Crocker	Lower Howell	
Emerald Lake #1	Upper Howell	
Pilarcitos	Cowell	
Notre Dame	Chabot	
Bear Gulch	Pacific Grove	
Lagunita	Forest Lake	
Belvedere		
Lagunitas		
Estates		
Berryman		
Lake Temescal		
Old San Andreas		
Summit		
Lake Ralphine		
Port Costa		
Lake Chabot		
Lake Herman		
Upper St. Helena		
Lower St. Helena		
Lake Camile		
Lake Frey		

¹"Predominantly Clay": greater portion of the material encountered consists of, for example, sandy <u>clays</u>, silty <u>clays</u>, lean <u>clays</u>.

²"Mixed Sands and Clays": material encountered consists of approximately equal portions of say, sandy <u>clay</u> and clayey <u>sand</u>.

³"Predominantly Sands": greater portion of the material encountered consists of, for example, clayey <u>sand</u> or silty <u>sand</u>.

* Reservoir totally lined concrete.

** Reservoir filled only few months before earthquake--fill probably not saturated.

Bedrock	Predom. Clay	Mixed Clays and Sands	Predominantly Sands
Lake Ranch	San Andreas	Lagunita	University Mound N. Basin
Lower Howell	Old San Andreas	Estates	
Upper Howell	Burlingame	Piedmont	
Notre Dame	Crocker	Pacific Grove	
Bear Gulch	Pilarcitos		
Lake Temescal	Lagunitas		
Upper St. Helena	Berryman		
Lower St. Helena	Chabot		
Lake Frey	Summit		
Lake Camille	Lake Chabot		
	Lake Herman		
	Cowell		
	Upper Crystal Springs		
	Emerald Lake #1		
	Belvedere		NOT REPRODUCIBLE
	Lake Ralphine		·····
	Port Costa		

Table 6: CLASSIFICATION OF DAMS ACCORDING TO TYPE OF FOUNDATION MATERIAL

the extent of this damage, together with information on the heights of the embankments and the estimated maximum accelerations developed in rock. Except in the case of one dam, Lower Howell, where a breach formed due to water escaping from a ruptured outlet pipe, damage to the other four was restricted to minor cracks and settlement and all embankments remained operational without any need for repairs; this in spite of the fact that the fault passed through the Upper Crystal Springs Dam and within 100 ft of the abutments of the San Andreas, Upper Howell and Lower Howell Dams. The behavior of the Upper Crystal Springs Dam was not considered of particular significance, however, since it had water at equal heights on both sides and was used only as a causeway at the time of the earthquake.

Thus the remarkable fact emerges that 32 dams were shaken severely by an 8-1/4 magnitude earthquake without sustaining any significant damage. It has been determined that the inclination of the slopes did not offer any added feature for stability; nor did their method of construction provide any added advantage; in fact, construction procedures can be considered less than adequate by today's standards of compaction procedures.

The one feature found common to most of the dams is the clayey nature of the embankment material and foundation soils. Most of the embankments consisted of clayey soils of low to medium plasticity, and considering the wide variation in their slopes and the uncontrolled and probably substandard methods of compaction employed in constructing them, it seems reasonable to conclude that the behavior of the clayey soils was the major factor contributing to their stability.

Two embankments, however, (University Mound and Piedmont) were found to consist predominantly of sandy material. Located at distances of 5 and 18 miles from the fault, their adequate performance does not conform with

the expected behavior of relatively loose saturated sands under conditions of strong shaking. Accordingly these two embankments were examined more closely to determine the reasons contributing to their stability. In the following paragraphs a description of the characteristics of the two embankments is presented along with the reasons for their adequate behavior.

University Mound North Basin:

Located about 5 miles from the fault, this dam has a height of 24 feet with upstream slopes of 3:1 and 1-1/2:1 and a downstream slope of 2:1. The embankment consists of predominantly silty sand (a product of the Colma formation) and some clayey gravels and clayey sands (a product of the Franciscan formation).

Its foundation is the Colma formation which consists of dense to very dense silty sand of the Pleistocene age.

The inside walls and the floor of the reservoir are lined with reinforced concrete to make it water tight. This condition would seem to eliminate the possibility of the embankment being saturated and would thus serve to explain its adequate behavior. The water table was encountered recently at a depth of 25 feet into the foundation (in the month of October); during the winter season the water table would still be within the foundation zone, which as mentioned earlier consists of very dense material and as such presents no problems of instability.

It thus appears that the dry condition of the embankment and the denseness of the foundation material were primarily responsible for the adequate behavior of the dam during the earthquake.

Piedmont Reservoir:

Located at approximately 18 miles from the zone of energy release, this dam has a height of 50 feet and upstream and downstream slopes of 2:1. The embankment consists of predominantly medium dense (non-plastic) silty sand and clayey sands and some sandstone fragments. The material was spread in thin layers, watered, and compacted by rollers. The average dry density of the embankment material was of the order of 115 pcf with a water content of 17%, and a relative compaction of approximately 97% based on standard AASHO maximum densities. The foundation material consisted of a layer of residual soil consisting of medium dense clayey sand and some sandy clays, underlain by a layer of "weathered overburden" consisting of very stiff sandy clays and dense clayey sands with dry densities between 112 and 116 pcf and water content values of 17 to 19%.

One very important factor is the fact that the dam was completed in 1905 and the reservoir filled for the first time only a few months before the earthquake (Ambraseys, 1960). In addition, the upstream face was lined with 6" thick reinforced concrete slabs with the construction joints sealed with asphalt. Considering also the impervious nature of the dense silty and clayey sand embankment, it again seems unlikely that any sizeable portion of the embankment would be in a saturated condition during the earthquake. The possibility of the foundation being saturated does exist, however, especially since the floor of the reservoir is not lined. But considering the confining pressures due to the total weight of the embankment, and the denseness and the clayey content of the foundation soils, the foundation is not expected to cause any problems of instability.

Thus the behavior of the University Mound North Basin and Piedmont embankments seems quite reasonable due to the following two reasons:

 The embankments were not saturated, and thus the potential for liquefaction and strength loss did not exist,

2) The foundation material seems to be strong enough to preclude any

possibility of failure resulting in instability of the embankment. In all other cases, it seems likely that the clayey nature of the construction materials, which generally exhibit little tendency for strength loss during shaking, was responsible for the excellent performance of the embankments.

Performance of Embankment Dams in the 1939 Ojika (Japan) Earthquake

The Ojika earthquake of 1939 was a magnitude 6.6 event which occurred in the northwestern portion of Honshu, Japan, causing estimated acceleration intensities in the zone of severe damage of the order of 0.3 to 0.4g.

A substantial number of low embankment dams forming reservoirs for irrigation purposes were damaged during the earthquake. As a result, a comprehensive survey (Akiba and Semba, 1941) was undertaken to investigate the damage to these embankments. A total of 74 embankments were severely damaged, of which 12 failed completely. Detailed surveys were made of 58 of the damaged embankments together with 12 which suffered no significant damage due to the shaking. The heights of the embankments ranged between 5 and 60 feet, but there was no apparent correlation between the height of an embankment and the extent of damage it experienced. Similarly although embankment construction records were found for 31 of the embankments investigated, no relationship between damage pattern and construction procedures could be determined.

Table 7 shows a breakdown of the number of embankments associated with different types of damage. It shows that slope failures and cracks (bulging being considered as a mild slope failure) were causes of damage in at least 80% of the embankments, with the type of damage being undetermined for most of the others due to the fact that they suffered complete failure. The grain size distributions for the embankment materials comprising the 12

Table 7: OJIKA EARTHQUAKE - RESERVOIR DAMAGE* Statistics on slope failures and crack development Upstream slope failure 17 Downstream slope failure 6 Both upstream and downstream slope failure 8 9 Undetermined due to complete failure Undetermined (others) 2 Cracking and bulding 6 Bulging only 1 Cracking only (primarily vertical) 9 58

After Akiba and Semba (1941)

Table 8: DAMAGE TO DAMS IN OJIKA EARTHQUAKE 1939*

Dam No.	> <u>0.1 mm</u>	0.01 to 0.1 mm	< <u>0.01 mm</u>	Notes
1	85	15	0	
2	84	15	1	
3	82	15	3	
4	66	18	16	
5	72	21	9	
6	79	12	9	
7	77	13	10	
8	92	5	3	
9	81	6	13	
10	34	38	28	Failure in poorly
11	14	59	27	compacted material over outlet conduit
12	36	31	33	Failure of conduit leading to piping

Grain Size Distribution for Dams Suffering Complete Failure

After Akiba and Semba (1941)

embankments which failed completely is shown in Table 8. As may be seen from the data in this table, 9 of these 12 embankments were constructed primarily of sands. For the three failures occurring in embankments constructed of clayey sands, two of the failures were found to be due to a washout of poorly compacted soil over recently repaired outlet conduits while the third was due to rupture of an outlet conduit which led to piping.

Of particular interest are the main conclusions reported by the authors of this study (Akiba and Semba, 1941) as follows:

- There were very few cases of dam failures during the earthquake shaking. Most of the failures occurred either a few hours or up to 24 hours after the earthquake.
- 2. The majority of the damaged and failed embankments consisted of sandy soils; no complete failure occurred in embankments constructed of clay soils.
- 3. Even at short distances from the epicenter, there were no complete failures among the embankments built of clayey soils; however, at greater epicentral distances, there was a heavy concentration of completely failed embankments composed of sandy soils.

This experience provides further evidence of the vastly superior stability of embankments constructed of clay soils under strong seismic loading conditions. It also suggests that the critical period for an embankment dam subjected to embankment shaking is not only the period of shaking itself but also a period of hours following an earthquake, possibly because piping may occur through cracks induced by the earthquake motions or slope failures may result from pore pressure re-distribution.

Performance of Embankment Dams in the 1952 Kern County (California) Earthquake

The embankments shaken by this earthquake provide a comparison between the behavior of rolled fill embankments of clayey material and the comparatively poorer performance of hydraulic fill dams of sandy material. The earthquake registered 7.6 on the Richter magnitude scale and shook the better part of Kern County and the northern part of Los Angeles County. Seven embankments, ranging in height between 20 and 190 feet were located within 50 miles of the epicenter where the shaking intensity ranged from very strong to moderate; some damage occurred however at one dam (South Haiwee) at a distance of 95 miles from the zone of energy release. Table 9 shows the heights of the affected embankments, their distance from the fault, the estimated base accelerations, the type of embankment material and construction procedure, and a summary of the reported damage.

As can be seen from Table 9, of the three hydraulic fill sandy embankments, two suffered longitudinal cracking with one (Dry Canyon) developing cracks indicative of a potentially incipient sliding condition. The estimated shaking intensities at these two embankments were approximately 0.12g and 0.04g. In contrast, three rolled fill embankments of compacted sandy clays subjected to estimated accelerations ranging between 0.06g and 0.12g, suffered no significant damage.

Fairmont Dan, however, which is also a hydraulic sand fill embankment located about 36 miles from the fault, was shaken by estimated accelerations of the order of 0.18g and suffered no significant damage.

The settlements reported in the Buena Vista embankment were due to cavities caused by leaching of gypsiferous beds in the foundation (Esmiol, 1965), and thus were not considered representative of the behavior of the embankment.

Again in this case there was no correlation between the heights and slopes of the embankments and their performance during the earthquake. However, the consistent pattern of behavior observed in the previous cases was also noticed in this earthquake; namely, that embankments of compacted clayey material at relatively short distances from the epicenter faired much better than embankments of sandy material at larger distances from the fault and at much lower shaking intensities.

Performance of Embankment Dams in the 1954 Fallon (Nevada) Earthquake

Two earthquakes with magnitudes about 6.7 occurred near Fallon, Nevada on July 6 and August 23, 1954, producing local ground motions of Modified Mercalli Intensity VIII to IX, corresponding to peak ground accelerations of the order of 0.25 to 0.4g in the near-epicentral region (Trifunac and Brady, 1976).

Damage to water supply facilities and embankment dams in the area is reported by Ambraseys (1960): "Extensive damage was caused to canal and drainage facilities of the Newlands Project. Culverts collapsed and longitudinal cracking and sloughing occurred in many places along both drainage channels and irrigation canal embankments. Canal levees settled from 1 to 3 ft and the bottoms of canals were raised by 1 to 2 ft. In one case the bottom of a drainage ditch was raised by 6 ft....At the Wildlife Area, the East Canal was severely damaged for about 2 miles and 200 yds were completely destroyed. West of Fallon a 40 ft portion of embankment, about 20 ft high failed completely..."

Damage to embankment dams was reported by Ambraseys (1960) as follows: Lahoutan Dam

"The foundation material (for this dam) consists of seamy broken sandstone and shale of varying degrees of hardness. The overburden, composed

		¥
HQUAKE		
EARJ	ed	5
COUNTY	Estimat	
KERN		
1952	fault	
	from	1 1 0 0
Table	Dist.	
	Ĕ	

	Date of	Height	Dist. from fault	Estimated		
Dam	Const.	-ft	-miles	Max. Accn.	Type of Fill	Effect of Earthquake
Tejon Storage	1946	32	4	≃0 . 6g	Rolled fill (sandy clay)	No significant damage
Buena Vista	1890	20	19	≈0 . 3g	Unknown	<pre>1 to 2 ft settlement over cavities in gypsum beds</pre>
Fairmont	1912	121	36	≃0.18g	Hydraulic fill	No reported damage
Drinkwater	1923	105	42	≃0 . 13g	Rolled fill	No damage
Dry Canyon	1912	66	45	≃0.12g	Hydraulic fill (sand, silty sand)	Longitudinal cracks along crest
Bouquet Canyon	1934	190	46	[≃] 0.12g	Rolled fill (sandy clay)	No damage
South Haiwee	1913	81	95	≃0 . 04g	Hydraulic fill (sand, clayey silt)	Slight cracking

* Table 10: EARTH DAMS DAMAGED BY THE TOKACHI-OKI EARTHQUAKE

	Under 10	meters	Over 10 1	meters
	Number	96	Number	96
Sliding causing failure	6	10.5		12.5
Sliding of upstream slope	21	24.7	4	50.0
Sliding of downstream slope	10	11.7	0	0
Sliding of both slopes	4	4.7	0	12.5
Cracking in dam body	24	28.2	Ч	12.5
Settlement of dam	7	8.2	1	12.5
Damage of appurtenant structures	22	25.8	2	25.0
Note: Number of dams investigated - 93 earth Dams under 10 meters high - 85 Dams over 10 meters high - 8	dams		x	

19

When two or more types of damage were found in the dam, they were counted separately.

of sandy clay and gravel, was removed and the dam was built on mudstone and stiff clay." The dam was located about 30 miles from the epicenter of the earthquakes, where peak ground accelerations may be expected to be about 0.15g, and apparently sustained no damage from either shock.

Coleman Dam

"This is a composite concrete-earth diversion structure and it is located one mile north-west of Fallon. Reports indicate that the structure was destroyed during the earthquake. This structure failed because of displacement and cracking of the earth-fill abutments, which in turn permitted water to erode around the concrete portion, causing it to partially overturn, crack and settle. The earth abutments were completely washed out."

Rogers Dam

"This dam was reported to have failed during the August 23rd earthquake in Fallon. No details were found but it appears that the structure, like Coleman Dam, was composed of a central concrete spillway with two earth-fill embankments. It was situated 3 miles north-east of Lovelock in Nevada. The southeast part of the dam composed of earth-fill gave way and a portion of the concrete structure was broken off and turned around into the spilling basis."

Performance of Embankment Dams in the 1968 Tokachi-Oki (Japan) Earthquake

This earthquake, with magnitude 7.8, caused extensive damage to embankments in the Aomori Prefecture in the northern tip of the main island of Honshu, Japan. The shaking intensity in the damaged area had peak accelerations of the order of 0.15 to 0.2g. Most of the embankments were small earth structures used for irrigation purposes with heights ranging between 15 and 60 feet. The embankment material consisted mostly of loose volcanic sand characterized by low values of standard penetration resistance constructed on foundation materials of a similar nature. A study of the damage to these embankments was reported by Moriya (1974). Table 10 shows a statistical summary of the type of damage observed in the 93 embankments investigated. It shows that sliding in the upstream and downstream slopes (or both) was the reported cause of damage in at least 50% of the embankments under 30 feet in height, and in 75% of the embankments over 30 feet in height. In 12% of the cases the sliding resulted in complete failure of the embankment. The slopes, in embankments under 30 feet ranged between 1:1.5 for the downstream face and 1:2.5 for the upstream face, while those for embankments over 30 feet ranged between 1:2.5 and 1:3.5 for the downstream and upstream sides respectively. There was no observed correlation between the slopes of the embankments and their performance during the earthquake. Most of the embankments were of homogeneous section; however, some were constructed with an impervious clay central core and it was noted that "sliding of the downstream slope did not occur in center-core dams with good water-tightness."

It seems likely from the above summary that slope failures in these embankments, as with those of the Ojika 1939 earthquake, can be attributed primarily to the phenomenon of liquefaction and/or strength loss associated with cyclic loading effects in loose saturated sands, leading to sliding and slumping mostly in the upstream slope and in some cases to complete failure of the embankment.

Performance of Embankment Dams in the 1971 San Fernando (California) Earthquake

A large number of earth dams in the County of Los Angeles were shaken by the 1971 San Fernando earthquake which registered a magnitude of 6.6 on the Richter scale. Within a 25-mile radius around the epicentral region (see Figure 2) some 44 dams, ranging in height between 30 and 190 feet, were subjected to peak accelerations of the order of 0.2 to 0.7g.



Fig. 2. DAMS LOCATED WITHIN 25 MILES OF THE EPICENTRAL REGION - SAN FERNANDO 1971 EARTHQUAKE.

The available information on these embankments in terms of their height, type, distance from fault, estimated base acceleration, and their performance during the earthquake is shown in Table 11. Of the 44 embankments listed in Table 11, 13 were non-operational (empty reservoir) during the earthquake and one was not saturated, so that only 30 of the embankments may be considered representative of fully operational dams. Of these operational embankments, 25 consisted of rolled fill dams of compacted clayey materials, and 5 were hydraulic sand fill dams. Whereas there was no damage observed in any of the 25 rolled fill embankments, two of the 5 hydraulic fill dams (Upper and Lower San Fernando dams) suffered substantial damage and major slides (Seed et al, 1973). The intensity of shaking at these two embankments was of the order of 0.5 to 0.6g. The shaking was of sufficient intensity and duration to induce large pore pressures in the saturated sandy embankments resulting in liquefaction and loss of strength. In the case of the Lower Dan the extent of the liquefied zone resulted in a major slide on the upstream side. In the Upper Dam, however, the result was a slide movement of 5 feet in the downstream direction and a crest settlement of 3 feet. The behavior of the Lower San Fernando Dam was typical of failures observed in the sandy embankments of the Ojika and Tokachi-Oki earthquakes in Japan.

However, the remaining 3 hydraulic fill embankments (Fairmont, Lower Franklin, and Silver Lake), all subjected to estimated maximum acceleration levels of the order of 0.2g performed adequately and suffered no significant damage. A summary of the performance of hydraulic fill dams with reference to the accelerations developed is presented in Table 12.

The contrasting behavior between rolled fill embankments and hydraulic fill embankments during this earthquake is essentially the same as that observed during the Kern County earthquake.

EARTH DAMS WITHIN 25 MILES OF EPICENTRAL REGION - SAN FERNANDO EARTHQUAKE. Table 11:

Damage	Minor cracking of embankment	No significant damage	No significant damage	SLIDE MOVEMENT DIT. DOWNSLEED	No significant damage	some stumping of embankment	some cracking in empanyment	No significant damage	Major silde upstream	No significant damage																																			
Reservoir Condition	Empty	Filled with debris	Empty	Operational	Empty	Empty	Empty	Operational	Operational	Empty	Operational	Operational	Empty	Operational	Operational	Empty.	Operational	Operational	Empty	Operational	Operational	Operational	Operational	Operational	Empty	Operational	Empty	Operational	Operational	Operational	Empty	Operational	Operational	Operational	Operational	Operational									
Height		166	49	82	66	36	43		142	97	117	105	41	190	35	44	96	28	57	30	60	168	200	35	41	87	55	110	62	185	121	103	113	29	55	12	20	34	50	53	63	73	72	146	
Estimated max. Rock Acceleration (g)	0.70	0.6	.68	. 55	. 55	. 55	. 55	. 50	. 50	.43	.43	.43	.40	.36	. 29	.28	.28	.27	.27	.25	.24	. 24	. 24	.23	.23	.23	.23	.23	. 22	.22	.20	.20	.20	.20	.20	.20	.20	.19	.19	.19	.19	.18	.18	.17	dor re-construction
Approx Distance From Epicentral Region (Miles)	34	ഗ്	54	0	50	53	61	- 1	~ -	6	6	6	10	11	14	14%	15	154	154	164	17	17	17	16	18	18	18	18	19	19	20	20	20	20	20	20	20	21	21	21	21	22	. 22	23	+++ (1) ++ (1)
Type	Rolled fill	Kolled fill	Kolled fill	Undergulic fill	D-11-3 5111	Dolled Fill	LILI DALLON	Kolled Fill	TTTI STIMPING	KOLLEG TILL	Kolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Hydraulic fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Hydraulic fill	Hydraulic fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	Hydraulic fill	Rolled fill	Rolled fill	Rolled fill	Rolled fill	
Dam	Wilson Debris	Lupez	Hunner Sim Foundation	Urv Canuch	Can Fornando Dito B	Channel Diversion Dite	ANTO NOTETANTO TANIDA	tower Can Fornando	Vance Juli Fernando		Green veraugo	DIINKWATEY	Porter Estate	Bouquet Canyon	Reservoir No. 1	Chatsworth	Brand Park	10th and Western	Sepulveda	Harold	Diederich	Encino	Santa Felicia	Chevy Chase	Runkle	Upper Hollywood	Upper Franklin	Upper Stone Canyon	Glenoaks	Stone Canyon	Fairmont	Lower Franklin	Eagle Rock	Rowena	Rubio Div. Debris	Highland	Ivanhoe	Sawtell	J.W. Wisda	Silver Lake	Eaton Wash	Ascot	Elysian	Wood Ranch	# Embackmant act active

Table 12: DAMAC	JE TO HYDRAULIC FI	ILL DAMS WITH	HIN 25 MILES OF EPICEN	TRAL REGION - SAN FERNANDO EARTHQUAKE, 1971
Dam	Approx. distan epicentral regio	nce from on - miles	Approx. max. rock accelerations	Performance
Upper San Fernando	Q		≃0 . 55g	Crest slid downstream 5 ft
Dry Canyon	6-1/2		≃0.55g	Not in use - reservoir empty - no damage
Lower San Fernando	7		≃0 . 50g	Major slide upstream
Chatsworth	14-1/2		ł	Under reconstruction - reservoir empty
Fairmont	20		≃0.20g	No significant damage
Lower Franklin	20		≃0.20g	No significant damage
Silver Lake	21		≃0 .1 9g	No significant damage
			·	
Table 13:	PERFORMANCE DUR	ING EARTHQUAI (see mater:	KES OF FIVE DAMS WITH Lal characteristics in	SANDY SHELLS AND CENTRAL CLAY CORES (Fig. 3)
Dam	(K ₂)*		Field	Performance
Chabot	65	Survived me damage; woi	agnitude 8-1/4 earthqu 1d apparently survive	lake at distance of 20 miles with no apparent magnitude 7 earthquake at distance of 2 miles.
Lower Franklin	50	Survived ma with no apj	agnitude 6-1/2 earthqu parent damage.	lake at distance of about 20 miles (a \gtrsim 0.2g)
Fairmont	50	Survived ma with no apj	agnitude 6-1/2 earthqu parent damage.	lake at distance of about 20 miles (a $\approx 0.2g$)
Lower San Fernando	45	Major upsti quake at di indicate da out signifi 8-1/4 eartl	ceam slide including u lstance of about 5 mil am would have survived lcant damage but would nquake at distance of	<pre>pper 30 ft of dam due to magnitude 6-1/2 earth- es (a ≈ 0.55g); performance and analysis l same earthquake at distance of 20 miles with- l have failed catastrophically for magnitude 20 miles.</pre>
Upper San Fernando	30	Downstream distance o: downstream tributed to	slide movement of cre f about 5 miles (a berm which together w) its better performan	st of dam due to magnitude 6-1/2 earthquake at $\approx 0.55g$; this embankment had an extremely wide ith its lower value of $(K_2)_{max}$ no doubt concide than the Lower San Fernando dam.

*Shear modulus G = 1000 K₂ ($\sigma_m^{1/2}$

-



Fig. 3. CYCLIC LOADING CHARACTERISTICS OF CONSTRUCTION MATERIALS FOR FIVE DAMS WITH KNOWN PERFORMANCE DURING STRONG EARTHQUAKE SHAKING (See Table 13). On the basis of the behavior of these embankments, it seems reasonable to conclude that hydraulic fill embankments generally are more susceptible to damage and failure than rolled fill embankments when subjected to earthquake shaking. This in no way indicates, however, that all hydraulic fill dams are inherently unstable; on the contrary, the performance record of the Fairmont, Lower Franklin and Silver Lake Dams shows that dams of this type can withstand shaking intensities of the order of 0.2g with no significant damage. At the same time the performance of a wide variety of rolled earth dams in this earthquake clearly shows that reasonably well-built structures of this type can withstand the shaking of a magnitude 6.5 earthquake, even in regions where the peak acceleration ranges from 0.2 to 0.5g, without significant damage.

The majority of the embankments consisted of clayey soils of medium to low plasticity. Thus their performance can be considered as confirmation of the excellent performance of embankments constructed of clayey soils in the 1906 and other earthquakes.

Quantitative data relating the material characteristics and the earthquake performance of hydraulic fill and wagon rolled earth fill dams in the San Francisco (1906) and San Fernando (1971) earthquakes is presented in Fig. 3 and Table 13. In general the three basic embankments parameters likely to have a major influence on the performance of a dam with reasonably full reservoir during an earthquake are:

- 1. The geometry of the dam; except in special circumstances, this is usually quite similar for most older dams.
- 2. The stiffness of the soils comprising the dam which influences the stresses induced by the earthquake. In the case of dams constructed of cohesionless soils, this may be approximately designated by the soil parameter $(K_2)_{max}$ in the equation for the shear modulus is

$$G = 1000 \text{ K}_{2} (\sigma_{m'})^{1/2} \text{ psf}$$

where G is the shear modulus of the soil and σ ' is the mean effective principal stress. In a general way, "the stiffer the material comprising the dam, the higher will be the stresses induced in it by any given earthquake motion.

3. The resistance of the soils comprising the shell of the dam to pore pressure build-up and strain development under cyclic loading conditions. This may be represented by data of the type shown in Fig. 3.

The results of cyclic load rests at a standard confining pressure of 1 kg per sq cm, and the corresponding values of $(K_2)_{max}$ for 5 dams with sandy shell materials whose performance is known (see Table 13) during specific earthquakes is shown in Fig. 3. The possible performance of other dams of the same general type (sand shells with central clay core) can often be evaluated from this data by direct comparison of material characteristics and prior prototype performance.

Performance of Embankment Dams in Other Earthquakes

While the performance of embankment dams in the six earthquakes described previously each provide data on the behavior of multiple structures in the same event, there are a number of other cases of known dam performance which merit the attention of the design engineer:

1. Mexico Earthquake, 1915

Failure of the Volcano Lake Dike is reported to have occurred during an earthquake in Mexico in 1915, probably as a result of liquefaction of loose foundation soils.

2. Kanto Earthquake (Japan), 1923

During the Kanto earthquake of 1923 (with a magnitude of 8.2) damage developed in three earth dams located at some distance from the epicenter where the maximum ground accelerations were estimated to be of the order of 0.3g. Reported damage is as follows (Moriya, 1974):

- Ono Dam: This dam was constructed in 1912; many fissures 2" to 10" wide developed along the crest of the dam ranging from 100 to 180 ft in length and extending to a depth of about 35 ft. One fissure was 70 ft deep. In addition, two local slides occurred on the downstream side of the dam.
- Lower Murayama Dam: This was a rolled fill dam with a puddle clay core; longitudinal cracks developed along the crest accompanied by outwards movement of the downstream slope. The downstream berm settled about 4 ft and moved downstream about 6 ft with a heaving of 2 ft near the downstream toe. Upper Murayama Dam: This dam was under construction at the time of the earthquake but a deep longitudinal crack about 1" wide formed in the completed portion of the embankment.

3. Santa Barbara (California) Earthquake, 1925

This earthquake reportedly had its epicenter about 7 miles northwest of the Sheffield Dam site and has been assigned a magnitude of 6.3. Reliable observers report that the shaking in the area of the dam had an intensity of about IX on the Rossi-Forrel scale which would correspond roughly to a peak acceleration of the order of 0.05 to 0.10g. However, an earthquake of magnitude 6.3 occurring at a distance of 7 miles is likely to produce ground accelerations substantially higher than these values.

The shaking produced a complete failure of the dam, reports indicating that sliding occurred near the base of the embankment causing a section of the dam about 300 ft in length to move bodily downstream as much as 100 ft, breaking up as it did so.

The embankment, about 720 ft long and having a maximum height of 25 ft was composed of silty sand and sandy silt but the upstream slope was faced with a 4-ft thick clay blanket which was extended as much at 10 ft down into the foundation to serve as a cut-off. The foundation soil consisted mainly of silty sand and sandy silt containing some cobbles. The upper 2 ft was somewhat looser than the underlying soil, having a relative density of the order of about 40 percent and it was apparently in this layer that the sliding occurred, since there was no formal stripping of this upper layer prior to construction. Examination after the failure indicated that there was no leakage of water through the upstream core but that seepage around and underneath the cut-off had saturated the foundation soils and the lower part of the main structure. At the time of the failure, the depth of water in the reservoir was about 15 to 18 ft (Seed et al, 1967).

4. Chile Earthquake, 1943

A strong earthquake (Magnitude 8.3) shook a number of dams in Chile in the earthquake of April 6, 1943. One of these, the Cogoti dam was subjected to shaking of intensity IX on the Rossi-Forrel scale corresponding to a peak acceleration of the order of 0.1g.

The dam was constructed of dumped rockfill with a laminated concrete facing on the upstream slope which served as the sole impervious element of the embankment. As a result of the earthquake, the crest of the embankment settled 15 inches and these were minor rock slides on the downstream slope. Overall damage to the structure, however, was insignificant.

5. El Centro Earthquake, 1940

Failure is known to have occurred in several dykes and canal banks during this earthquake (Ross, 1968), which had a magnitude of about 6.6.

Ground accelerations in the area of damage are estimated to be of the order of 0.2 to 0.5g and failure was apparently due to liquefaction of foundation soils.

6. Russian Earthquakes

Several hydraulic fill dams in Russia have been subjected to earthquake motions ranging from about 0.10g to 0.17g with little or no damage (Ambraseys, 1960). Data on the particular dams involved and their performance are summarized in Table 14.

7. Nankai Earthquake (Japan), 1946

During this earthquake, (Magnitude \approx 8.1), approximately 50 dams constructed between 760 and 1944 with heights ranging from 50 to 130 ft were subjected to ground motions with peak accelerations estimated to range from 0.08g to 0.25g with no reports of damage.

8. Fukui Earthquake (Japan), 1948

Failure occurred in the Hosorogi embankment located in an area where the maximum ground acceleration was estimated to be about 0.45g. The embankment was constructed of silty clay on a foundation of soft organic silt. Failure was apparently due to lateral spreading and settlement of the embankment into the foundation soil (Ambraseys, 1960).

9. Hebgen Lake Earthquake, 1959

The Hebgen Lake earthquake (Magnitude \simeq 7.6) of August 17, 1959, occurred on a fault located only a few hundred feet from the Hebgen Dam, a compacted earth fill structure constructed on foundation soil with depths ranging from 10 to 90 ft and provided with a central concrete core wall extending through the dam and foundation soils to the underlying rock. The fault ran parallel to the reservoir and fault movements were essentially

vertical, resulting in a lowering of the dam and reservoir of about 10 ft due to tectonic movements and a corresponding rise in ground level on the upthrown side of the fault.

Ground shaking in the vicinity of the dam was undoubtedly very strong and it produced the following effects on the dam: (1) settlement of the crest of the dam relative to the underlying rock; the maximum settlement was about 4 ft on the downstream side and 6 ft on the upstream side of the crest; (2) several cracks, the largest being about 3 inches wide in the concrete core wall; (3) severe longitudinal and some transverse cracking, with crack widths varying from 3 inches to 12 inches on the upstream and downstream sides of the crest; (4) some leakage near the abutment contact in the general vicinity of the core-wall cracks; this leakage stopped when the badly cracked spillway were sealed; (5) a number of waves in the reservoir which caused the crest to be overtopped at least four times for periods of about 10 minutes; the depth of water flowing over the crest was estimated at about 3 ft during the second of these overflows; (6) a number of landslides around the edges of the reservoir and (7) a massive rock-slide, estimated at about 50 million tons of rock which dammed up the river about 7 miles downstream and created a lake which backed up to the downstream toe of the dam.

Concerning this behavior, J. L. Sherard (1966) who visited the site immediately after the earthquake, and later made a detailed appraisal of the effects, reports as follows: "One does not have to reflect very long on the events which occurred before concluding that an extremely fortunate array of conditions prevented a complete failure--and with such a large reservoir, the failure would have been a disaster even in that sparsely populated area."

Fortunately the dam was constructed of a slightly cohesive well-graded sand and gravel which resisted erosion and the development of high pore

pressures during the earthquake shaking. Never-the-less, slumping on the upstream side amounted to about 7 percent of the height of the dam at some sections (Seed, 1968).

10. Kita-Muto Earthquake (Japan), 1961

This earthquake with magnitude 7 occurred with its epicenter about 20 kms from the Miboro Dam, a large rockfill structure 131 m high with a sloping upstream core, an upstream slope of 1 on 2.5 and downstream slope of 1 on 1.75. Ground motions in the rocky terrain in the area of the epicenter are said to have been of short period and violent; the shaking produced several large landslides and a great amount of falling rock (Okamoto, 1973).

Accelerations in the vicinity of the Miboro Dam are estimated to be within the range 0.1g to 0.25g but the only effects on the dam were a settlement of 3 cm and a horizontal displacement of 5 cm at the crest.

11. Alaska Earthquake, 1964

Failure occurred in the embankment of a private dam near Anchorage in the Alaska earthquake of 1964. The dam had a homogeneous section, about 20 ft high but no construction records are available. Ground accelerations in the area are estimated to have been about 0.15g (Seed, 1968).

Overall Summary

It is apparent from the reports presented in the previous pages that earth dams have fared both well and poorly when subjected to earthquake ground motions. An attempt to summarize all of the available data is presented in Tables 15, 16, and 17. Table 15 lists known failures and damages to earth dams due to earthquakes in the United States; Table 16 lists failures and damages to earth dams due to earthquakes in Japan; and Table 14: PERFORMANCE OF HYDRAULIC FILL DAMS IN RUSSIA

1944	Boz'suiskaya Dam	Fill dumped through water	a _{max} ~ 0.17g	About 1 ft settlement
1957	Kairakkumskaya Dam	Hydraulic fill	a _{max} ≃ 0.12g	No damage
1957	Minguechaurskaya Dam	Hydraulic fill	a _{max} ≃ 0.10g	No damage
				· .
				KUTTUME TIMUCHE

Table 15: DAMS KNOWN TO HAVE FAILED BY EARTHQUAKE ACTION IN NORTH AMERICA

Volcano Lake Dyke Sheffield Dam Private Dam Coleman Dam	Mexico California California Nevada	1915 1925 1952 1954	Loose foundation soils probably liquefied Liquefaction of loose silty sand near base (a _{max} ² 0.2g) Near epicentral region of Mag. 6.6 Eq.
kogers vam Private Dam	Anchorage	1964 1964	

Dams known to have major damage due to earthquake action in North America

Upper San Fernando Lower San Fernando	California California	1971 1971	5' downstream slide in hydraulic sand fill; a _{max} ≃ 0.55g Major upstream slope slide in hydraulic sand fill due to liquefaction; a _{may} ≃ 0.55g
Hebgen Dam	Nevada	1959	slumping and cracking of embankment; a _{max} ≃ 0.7g

.

Hosogori Embankment a _{max} ≃ 0.45. Silty clay embankment on soft organic silts. Failure due to base spreading and settlement of embankment into soil - nearby houses also settled about 3 ft into foundation.

Table 17: DAMS KNOWN TO HAVE ADEQUATE PERFORMANCE DURING EARTHQUAKES

<u>Rockfill</u> - <u>Miboro Dam</u>, Japan (420' high) - no damage from M = 7@ 10 km producing a $\simeq 0.6$.

> <u>Cogoti Dam</u> - concrete faced rockfill, 275' high; $a_{max} \simeq 0.25$ to 0.5g; 15" crest settlement; some sliding on downstream face @ 1 on 1.8.

<u>Clay Dams</u> - 31 earth dams of clay, sandy clay or clayey sand had negligible damage at shaking levels of 0.25 to 0.8g in San Francisco earthquake (1906). At least 12 irrigation dams constructed of clay soils were undamaged at shaking levels of 0.4 to 0.5g in Ojika earthquake (1948); sand dams had failures at lower shaking levels.

- Rolled earth dams 25 rolled earth fill dams with shaking levels ranging from 0.2 to 0.4g had no damage in San Fernando earthquake (1971).
- Hydraulic fill dams 3 hydraulic fill dams had no damage at shaking levels of about 0.2g in San Fernando earthquake (1971). 3 hydraulic fill dams in Russia had no failures at shaking levels of 0.10 to 0.17g approx. 2 hydraulic fill dams had minor damage at shaking levels of 0.12 to 0.18g in Kern County earthquake (1952).
- <u>Miscellaneous dams</u> 50 dams built between 760 and 1944 with heights ranging from 50 to 130 ft had no damage at shaking levels of 0.08 to 0.25g in Nankai earthquake in Japan (1944).

Table 17 lists the many cases where no failures or damage have occurred during major earthquakes in the United States, Japan, South America, and Russia.

A careful review of the experience presented in these tables would seem to lead to the following conclusions:

- Hydraulic fill dams have been found to be vulnerable to failures under unfavorable conditions and one of the particular unfavorable conditions is the shaking produced by strong earthquakes.
- 2. Many hydraulic fill dams, however, have performed well for many years and when they are built with reasonable slopes on good foundations they can survive moderately strong shaking--say up to about 0.2g from Magnitude 6-1/2 to 7 earthquakes with no harmfull effects.
- Virtually any well-built dam can withstand moderate earthquake shaking, say with peak accelerations of about 0.2g and more, with no detrimental effects.
- Dams constructed of clay soils on clay or rock foundations have withstood extremely strong shaking ranging from 0.35 to 0.8g from a magnitude 8-1/4 earthquake with no apparent damage.
- 5. Two rockfill dams have withstood strong shaking with no significant damage and if the rockfill is kept dry by means of a concrete facing they should be able to withstand extremely strong shaking with only small deformations.
- 6. Since there is ample field evidence that well-built dams can withstand moderate shaking with peak accelerations up to at least 0.2g with no harmful effects, we should not waste our time and money analyzing this type of problem--rather we should concentrate our efforts on those dams likely to present problems either because of strong shaking or because they incorporate large bodies of cohesionless materials (usually sands)

which, if saturated, may lose most of their strength during earthquake shaking and thereby lead to undesirable movements.

8. For dams constructed of saturated cohesionless soils and subjected to strong shaking, a primary cause of damage or failure is the build-up of pore water pressures in the embankment and the possible loss of strength which may accrue as a result of these pore pressures. Great caution is required in attempting to predict this type of failure by psuedo-static analyses, and dynamic analysis techniques seem to provide a more reliable basis for evaluating field performance.

A knowledge of field performance data of this type can provide a valuable supplement to analytical studies in the final assessment of the seismic stability of an earth dam and in some cases can eliminate entirely the need for analytical studies. In fact such knowledge of past performance, combined with guidance provided by dynamic analyses when appropriate, and the application of good judgment are the tools required to reach final decisions on the seismic stability of dams at the present time; with the aid of such information, it should indeed be possible to provide a higher degree of safety of dams against the damaging effects of earthquakes than ever before possible.

Acknowledgment

The study presented in the preceding pages was conducted under the sponsorship of the National Science Foundation (Grant No. ENV 75-21875) and the State of California Department of Water Resources. Considerable support was also provided by the Los Angeles Department of Water and Power. The support provided by all of these organizations is gratefully acknowledged.

Special thanks are also due to Professor Akiba who provided the authors with a Japanese report on the damage to dams in the Ojika earthquake and to Kenji Mori who translated this report.

References

Akiba, M. and Semba, H. (1941) "The Earthquake and Its Influence on Reservoirs in Akita Prefecture," Journal of the Agricultural Engineering Society, Japan, Vol. 13, No. 1, March.

Ambraseys, N. N. (1960) "On the Seismic Behavior of Earth Dams," Proceedings of the Second World Conference on Earthquake Engineering, Japan, 1960, Vol. I, pp. 331-354.

Esmiol, E. E. (1965) "Rational Earthquake Design Criteria for Earth Dams," United States Department of the Interior, Bureau of Reclamation, Office of Chief Engineer, Denver.

Moriya, M. (1974) "Damages Caused to Small Earthfill Dams for Irrigation in Armori Prefecture by Tokachi Offshore Earthquake," Report prepared for the Committee on Lessons from Incidents of Dam Failures, International Commission on Large Dams.

Okamoto, S. (1973) "Introduction to Earthquake Engineering," University of Tokyo Press, Published by John Wiley & Sons, Inc., New York.

Ross, G. A. (1968) "Case Studies of Soil Stability Problems Resulting from Earthquakes," Ph.D. Thesis, Department of Civil Engineering, University of California, Berkeley.

Schnabel, P. B. and Seed, H. B. (1972) "Accelerations in Rock for Earthquakes in the Western United States," Earthquake Engineering Research Center, Report No. EERC 72-2, University of California, Berkeley, July.

Seed, H. B. (1968) "Earthquake-Resistant Design of Earth Dams," Canadian Geotechnical Journal, Vol. IV, No. 1.

Seed, H. B., Lee, K. L., and Idriss, I. M. (1969) "An Analysis of the Sheffield Dam Failure," Journal of the Soil Mechanics and Foundations Division, ASCE, Vol. 95, No. SM6, Proc. Paper 6906, November, pp. 1453-1490.

Seed, H. B., Lee, K. L., Idriss, I. M., and Makdisi, F. (1973) "Analysis of the Slides in the San Fernando Dams during the Earthquake of February 9, 1971," Earthquake Engineering Research Center, Report No. EERC 73-2, University of California, Berkeley, June.

Trifunac, M. D. and Brady, A. G. (1976) "On the Correlation of Seismic Intensity Scales with Peaks of Recorded Strong Ground Motion," Bulletin of the Seismological Society of America, Vol. 65, No. 1, February.

- EERC 67-1 "Feasibility Study Large-Scale Earthquake Simulator Facility," by J. Penzien, J. G. Bouwkamp, R. W. Clough and D. Rea - 1967 (PB 187 905)
- EERC 68-1 Unassigned

EERC 68-2 "Inelastic Behavior of Beam-to-Column Subassemblages Under Repeated Loading," by V. V. Bertero - 1968 (PB 184 888)

- EERC 68-3 "A Graphical Method for Solving the Wave Reflection-Refraction Problem," by H. D. McNiven and Y. Mengi 1968 (PB 187 943)
- EERC 68-4 "Dynamic Properties of McKinley School Buildings," by D. Rea, J. G. Bouwkamp and R. W. Clough - 1968 (PB 187 902)
- EERC 68-5 "Characteristics of Rock Motions During Earthquakes," by H. B. Seed, I. M. Idriss and F. W. Kiefer - 1968 (PB 188 338)
- EERC 69-1 "Earthquake Engineering Research at Berkeley," 1969 (PB 187 906)
- EERC 69-2 "Nonlinear Seismic Response of Earth Structures," by M. Dibaj and J. Penzien - 1969 (PB 187 904)
- EERC 69-3 "Probabilistic Study of the Behavior of Structures During Earthquakes," by P. Ruiz and J. Penzien - 1969 (PB 187 886)
- EERC 69-4 "Numerical Solution of Boundary Value Problems in Structural Mechanics by Reduction to an Initial Value Formulation," by N. Distefano and J. Schujman - 1969 (PB 187 942)
- EERC 69-5 "Dynamic Programming and the Solution of the Biharmonic Equation," by N. Distefano - 1969 (PB 187 941)

Note: Numbers in parenthesis are Accession Numbers assigned by the National Technical Information Service. Copies of these reports may be ordered from the National Technical Information Service, 5285 Port Royal Road, Springfield, Virginia, 22161. Accession Numbers should be quoted on orders for the reports (PB --- ---) and remittance must accompany each order. (Foreign orders, add \$2.50 extra for mailing charges.) Those reports without this information listed are not yet available from NTIS. Upon request, EERC will mail inquirers this information when it becomes available to us.

- EERC 69-6 "Stochastic Analysis of Offshore Tower Structures," by A. K. Malhotra and J. Penzien - 1969 (PB 187 903)
- EERC 69-7 "Rock Motion Accelerograms for High Magnitude Earthquakes," by H. B. Seed and I. M. Idriss - 1969 (PB 187 940)
- EERC 69-8 "Structural Dynamics Testing Facilities at the University of California, Berkeley," by R. M. Stephen, J. G. Bouwkamp, R. W. Clough and J. Penzien - 1969 (PB 189 111)
- EERC 69-9 "Seismic Response of Soil Deposits Underlain by Sloping Rock Boundaries," by H. Dezfulian and H. B. Seed - 1969 (PB 189 114)
- EERC 69-10 "Dynamic Stress Analysis of Axisymmetric Structures under Arbitrary Loading," by S. Ghosh and E. L. Wilson - 1969 (PB 189 026)
- EERC 69-11 "Seismic Behavior of Multistory Frames Designed by Different Philosophies," by J. C. Anderson and V. V. Bertero - 1969 (PB 190 662)
- EERC 69-12 "Stiffness Degradation of Reinforcing Concrete Structures Subjected to Reversed Actions," by V. V. Bertero, B. Bresler and H. Ming Liao - 1969 (PB 202 942)
- EERC 69-13 "Response of Non-Uniform Soil Deposits to Travel Seismic Waves," by H. Dezfulian and H. B. Seed - 1969 (PB 191 023)
- EERC 69-14 "Damping Capacity of a Model Steel Structure," by D. Rea, R. W. Clough and J. G. Bouwkamp - 1969 (PB 190 663)
- EERC 69-15 "Influence of Local Soil Conditions on Building Damage Potential during Earthquakes," by H. B. Seed and I. M. Idriss - 1969 (PB 191 036)
- EERC 69-16 "The Behavior of Sands under Seismic Loading Conditions," by M. L. Silver and H. B. Seed - 1969 (AD 714 982)
- EERC 70-1 "Earthquake Response of Concrete Gravity Dams," by A. K. Chopra - 1970 (AD 709 640)
- EERC 70-2 "Relationships between Soil Conditions and Building Damage in the Caracas Earthquake of July 29, 1967," by H. B. Seed, I. M. Idriss and H. Dezfulian - 1970 (PB 195 762)

- EERC 70-3 "Cyclic Loading of Full Size Steel Connections," by E. P. Popov and R. M. Stephen - 1970 (PB 213 545)
- EERC 70-4 "Seismic Analysis of the Charaima Building, Caraballeda, Venezuela," by Subcommittee of the SEAONC Research Committee: V. V. Bertero, P. F. Fratessa, S. A. Mahin, J. H. Sexton, A. C. Scordelis, E. L. Wilson, L. A. Wyllie, H. B. Seed and J. Penzien, Chairman - 1970 (PB 201 455)
- EERC 70-5 "A Computer Program for Earthquake Analysis of Dams," by A. K. Chopra and P. Chakrabarti - 1970 (AD 723 994)
- EERC 70-6 "The Propagation of Love Waves across Non-Horizontally Layered Structures," by J. Lysmer and L. A. Drake -1970 (PB 197 896)
- EERC 70-7 "Influence of Base Rock Characteristics on Ground Response," by J. Lysmer, H. B. Seed and P. B. Schnabel - 1970 (PB 197 897)
- EERC 70-8 "Applicability of Laboratory Test Procedures for Measuring Soil Liquefaction Characteristics under Cyclic Loading," by H. B. Seed and W. H. Peacock -1970 (PB 198 016)
- EERC 70-9 "A Simplified Procedure for Evaluating Soil Liquefaction Potential," by H. B. Seed and I. M. Idriss - 1970 (PB 198 009)
- EERC 70-10 "Soil Moduli and Damping Factors for Dynamic Response Analysis," by H. B. Seed and I. M. Idriss - 1970 (PB 197 869)
- EERC 71-1 "Koyna Earthquake and the Performance of Koyna Dam," by A. K. Chopra and P. Chakrabarti - 1971 (AD 731 496)
- EERC 71-2 "Preliminary In-Situ Measurements of Anelastic Absorption in Soils Using a Prototype Earthquake Simulator," by R. D. Borcherdt and P. W. Rodgers -1971 (PB 201 454)
- EERC 71-3 "Static and Dynamic Analysis of Inelastic Frame Structures," by F. L. Porter and G. H. Powell - 1971 (PB 210 135)
- EERC 71-4 "Research Needs in Limit Design of Reinforced Concrete Structures," by V. V. Bertero - 1971 (PB 202 943)
- EERC 71-5 "Dynamic Behavior of a High-Rise Diagonally Braced Steel Building," by D. Rea, A. A. Shah and J. G. Bouwkamp - 1971 (PB 203 584)

- EERC 71-6 "Dynamic Stress Analysis of Porous Elastic Solids Saturated with Compressible Fluids," by J. Ghaboussi and E. L. Wilson - 1971 (PB 211 396)
- EERC 71-7 "Inelastic Behavior of Steel Beam-to-Column Subassemblages," by H. Krawinkler, V. V. Bertero and E. P. Popov - 1971 (PB 211 335)
- EERC 71-8 "Modification of Seismograph Records for Effects of Local Soil Conditions," by P. Schnabel, H. B. Seed and J. Lysmer - 1971 (PB 214 450)
- EERC 72-1 "Static and Earthquake Analysis of Three Dimensional Frame and Shear Wall Buildings," by E. L. Wilson and H. H. Dovey - 1972 (PB 212 904)
- EERC 72-2 "Accelerations in Rock for Earthquakes in the Western United States," by P. B. Schnabel and H. B. Seed -1972 (PB 213 100)
- EERC 72-3 "Elastic-Plastic Earthquake Response of Soil-Building Systems," by T. Minami - 1972 (PB 214 868)
- EERC 72-4 "Stochastic Inelastic Response of Offshore Towers to Strong Motion Earthquakes," by M. K. Kaul - 1972 (PB 215 713)
- EERC 72-5 "Cyclic Behavior of Three Reinforced Concrete Flexural Members with High Shear," by E. P. Popov, V. V. Bertero and H. Krawinkler - 1972 (PB 214 555)
- EERC 72-6 "Earthquake Response of Gravity Dams Including Reservoir Interaction Effects," by P. Chakrabarti and A. K. Chopra - 1972 (AD 762 330)
- EERC 72-7 "Dynamic Properties on Pine Flat Dam," by D. Rea, C. Y. Liaw and A. K. Chopra - 1972 (AD 763 928)
- EERC 72-8 "Three Dimensional Analysis of Building Systems," by E. L. Wilson and H. H. Dovey - 1972 (PB 222 438)
- EERC 72-9 "Rate of Loading Effects on Uncracked and Repaired Reinforced Concrete Members," by S. Mahin, V. V. Bertero, D. Rea and M. Atalay - 1972 (PB 224 520)
- EERC 72-10 "Computer Program for Static and Dynamic Analysis of Linear Structural Systems," by E. L. Wilson, K.-J. Bathe, J. E. Peterson and H. H. Dovey - 1972 (PB 220 437)

- EERC 72-11 "Literature Survey Seismic Effects on Highway Bridges," by T. Iwasaki, J. Penzien and R. W. Clough -1972 (PB 215 613)
- EERC 72-12 "SHAKE-A Computer Program for Earthquake Response Analysis of Horizontally Layered Sites," by P. B. Schnabel and J. Lysmer - 1972 (PB 220 207)
- EERC 73-1 "Optimal Seismic Design of Multistory Frames," by V. V. Bertero and H. Kamil - 1973
- EERC 73-2 "Analysis of the Slides in the San Fernando Dams during the Earthquake of February 9, 1971," by H. B. Seed, K. L. Lee, I. M. Idriss and F. Makdisi -1973 (PB 223 402)
- EERC 73-3 "Computer Aided Ultimate Load Design of Unbraced Multistory Steel Frames," by M. B. El-Hafez and G. H. Powell - 1973 (PB 248 315)A09
- EERC 73-4 "Experimental Investigation into the Seismic Behavior of Critical Regions of Reinforced Concrete Components as Influenced by Moment and Shear," by M. Celebi and J. Penzien - 1973 (PB 215 884) A09
- EERC 73-5 "Hysteretic Behavior of Epoxy-Repaired Reinforced Concrete Beams," by M. Celebi and J. Penzien - 1973 (PB 239 568)A03
- EERC 73-6 "General Purpose Computer Program for Inelastic Dynamic Response of Plane Structures," by A. Kanaan and G. H. Powell - 1973 (PB 221 260) A08
- EERC 73-7 "A Computer Program for Earthquake Analysis of Gravity Dams Including Reservoir Interaction," by P. Chakrabarti and A. K. Chopra - 1973 (AD 766 271)A04
- EERC 73-8 "Behavior of Reinforced Concrete Deep Beam-Column Subassemblages under Cyclic Loads," by O. Kustu and J. G. Bouwkamp - 1973 (PB 246 117)A12
- EERC 73-9 "Earthquake Analysis of Structure-Foundation Systems," by A. K. Vaish and A. K. Chopra - 1973 (AD 766 272)A07
- EERC 73-10 "Deconvolution of Seismic Response for Linear Systems," by R. B. Reimer - 1973 (PB 227 179) A08
- EERC 73-11 "SAP IV: A Structural Analysis Program for Static and Dynamic Response of Linear Systems," by K.-J. Bathe, E. L. Wilson and F. E. Peterson - 1973 (PB 221 967) A09
- EERC 73-12 "Analytical Investigations of the Seismic Response of Long, Multiple Span Highway Bridges," by W. S. Tseng and J. Penzien - 1973 (PB 227 816) Al0

- EERC 73-13 "Earthquake Analysis of Multi-Story Buildings Including Foundation Interaction," by A. K. Chopra and J. A. Gutierrez - 1973 (PB 222 970)A03
- EERC 73-14 "ADAP: A Computer Program for Static and Dynamic Analysis of Arch Dams," by R. W. Clough, J. M. Raphael and S. Majtahedi - 1973 (PB 223 763)A09
- EERC 73-15 "Cyclic Plastic Analysis of Structural Steel Joints," by R. B. Pinkney and R. W. Clough - 1973 (PB 226 843)A08
- EERC 73-16 "QUAD-4: A Computer Program for Evaluating the Seismic Response of Soil Structures by Variable Damping Finite Element Procedures," by I. M. Idriss, J. Lysmer, R. Hwang and H. B. Seed - 1973 (PB 229 424)A05
- EERC 73-17 "Dynamic Behavior of a Multi-Story Pyramid Shaped Building," by R. M. Stephen and J. G. Bouwkamp - 1973 (PB 240 718)A06

EERC 73-18 "Effect of Different Types of Reinforcing on Seismic Behavior of Short Concrete Columns," by V. V. Bertero, J. Hollings, O. Kustu, R. M. Stephen and J. G. Bouwkamp - 1973

- EERC 73-19 "Olive View Medical Center Material Studies, Phase I," by B. Bresler and V. V. Bertero - 1973 (PB 235 986)A06
- EERC 73-20 "Linear and Nonlinear Seismic Analysis Computer Programs for Long Multiple-Span Highway Bridges," by W. S. Tseng and J. Penzien - 1973
- EERC 73-21 "Constitutive Models for Cyclic Plastic Deformation of Engineering Materials," by J. M. Kelly and P. P. Gillis - 1973 (PB 226 024)A03
- EERC 73-22 "DRAIN 2D User's Guide," by G. H. Powell 1973 (PB 227 016) A05
- EERC 73-23 "Earthquake Engineering at Berkeley 1973" 1973 (PB 226 033)All
- EERC 73-24 Unassigned
- EERC 73-25 "Earthquake Response of Axisymmetric Tower Structures Surrounded by Water," by C. Y. Liaw and A. K. Chopra -1973 (AD 773 052)A09
- EERC 73-26 "Investigation of the Failures of the Olive View Stairtowers during the San Fernando Earthquake and Their Implications in Seismic Design," by V. V. Bertero and R. G. Collins - 1973 (PB 235 106) A13

- EERC 73-27 "Further Studies on Seismic Behavior of Steel Beam-Column Subassemblages," by V. V. Bertero, H. Krawinkler and E. P. Popov - 1973 (PB 234 172)A06
- EERC 74-1 "Seismic Risk Analysis," by C. S. Oliveira 1974 (PB 235 920)A06
- EERC 74-2 "Settlement and Liquefaction of Sands under Multi-Directional Shaking," by R. Pyke, C. K. Chan and H. B. Seed - 1974
- EERC 74-3 "Optimum Design of Earthquake Resistant Shear Buildings," by D. Ray, K. S. Pister and A. K. Chopra -1974 (PB 231 172)A06
- EERC 74-4 "LUSH A Computer Program for Complex Response Analysis of Soil-Structure Systems," by J. Lysmer, T. Udaka, H. B. Seed and R. Hwang - 1974 (PB 236 796) A05
- EERC 74-5 "Sensitivity Analysis for Hysteretic Dynamic Systems: Applications to Earthquake Engineering," by D. Ray -1974 (PB 233 213) A06
- EERC 74-6 "Soil-Structure Interaction Analyses for Evaluating Seismic Response," by H. B. Seed, J. Lysmer and R. Hwang - 1974 (PB 236 519) A04
- EERC 74-7 Unassigned
- EERC 74-8 "Shaking Table Tests of a Steel Frame A Progress Report," by R. W. Clough and D. Tang - 1974 (PB 240 869)A03
- EERC 74-9 "Hysteretic Behavior of Reinforced Concrete Flexural Members with Special Web Reinforcement," by V. V. Bertero, E. P. Popov and T. Y. Wang - 1974 (PB 236 797) A07
- EERC 74-10 "Applications of Reliability-Based, Global Cost Optimization to Design of Earthquake Resistant Structures," by E. Vitiello and K. S. Pister - 1974 (PB 237 231) A06
- EERC 74-11 "Liquefaction of Gravelly Soils under Cyclic Loading Conditions," by R. T. Wong, H. B. Seed and C. K. Chan -1974 (PB 242 042)A03
- EERC 74-12 "Site-Dependent Spectra for Earthquake-Resistant Design," by H. B. Seed, C. Ugas and J. Lysmer - 1974 (PB 240 953)A03

EERC 74-13 "Earthquake Simulator Study of a Reinforced Concrete Frame," by P. Hidalgo and R. W. Clough - 1974 (PB 241 944) A13

EERC 74-14 "Nonlinear Earthquake Response of Concrete Gravity Dams," by N. Pal - 1974 (AD/A006583) A06

EERC 74-15 "Modeling and Identification in Nonlinear Structural Dynamics, I - One Degree of Freedom Models," by N. Distefano and A. Rath - 1974 (PB 241 548) A06

EERC 75-1 "Determination of Seismic Design Criteria for the Dumbarton Bridge Replacement Structure, Vol. I: Description, Theory and Analytical Modeling of Bridge and Parameters," by F. Baron and S.-H. Pang - 1975 (PB 259 407)A15

EERC 75-2 "Determination of Seismic Design Criteria for the Dumbarton Bridge Replacement Structure, Vol. 2: Numerical Studies and Establishment of Seismic Design Criteria," by F. Baron and S.-H. Pang - 1975 (PB 259 408)All (For set of EERC 75-1 & 75-2 (PB 259 406)).

EERC 75-3 "Seismic Risk Analysis for a Site and a Metropolitan Area," by C. S. Oliveira - 1975 (PB 248 134)A09

EERC 75-4 "Analytical Investigations of Seismic Response of Short, Single or Multiple-Span Highway Bridges," by Ma-chi Chen and J. Penzien - 1975 (PB 241 454) A09

EERC 75-5 "An Evaluation of Some Methods for Predicting Seismic Behavior of Reinforced Concrete Buildings," by Stephen A. Mahin and V. V. Bertero - 1975 (PB 246 306)Al6

EERC 75-6 "Earthquake Simulator Study of a Steel Frame Structure, Vol. I: Experimental Results," by R. W. Clough and David T. Tang - 1975 (PB 243 981)A13

EERC 75-7 "Dynamic Properties of San Bernardino Intake Tower," by Dixon Rea, C.-Y. Liaw, and Anil K. Chopra - 1975 (AD/A008406) A05

EERC 75-8 "Seismic Studies of the Articulation for the Dumbarton Bridge Replacement Structure, Vol. I: Description, Theory and Analytical Modeling of Bridge Components," by F. Baron and R. E. Hamati - 1975 (PB 251 539)A07

EERC 75-9 "Seismic Studies of the Articulation for the Dumbarton Bridge Replacement Structure, Vol. 2: Numerical Studies of Steel and Concrete Girder Alternates," by F. Baron and R. E. Hamati - 1975 (PB 251 540)Al0

- EERC 75-10 "Static and Dynamic Analysis of Nonlinear Structures," by Digambar P. Mondkar and Graham H. Powell - 1975 (PB 242 434) A08
- EERC 75-11 "Hysteretic Behavior of Steel Columns," by E. P. Popov, V. V. Bertero and S. Chandramouli - 1975 (PB 252 365)All
- EERC 75-12 "Earthquake Engineering Research Center Library Printed Catalog" - 1975 (PB 243 711) A26
- EERC 75-13 "Three Dimensional Analysis of Building Systems," Extended Version, by E. L. Wilson, J. P. Hollings and H. H. Dovey - 1975 (PB 243 989)A07
- EERC 75-14 "Determination of Soil Liquefaction Characteristics by Large-Scale Laboratory Tests," by Pedro De Alba, Clarence K. Chan and H. Bolton Seed - 1975 (NUREG 0027)A08
- EERC 75-15 "A Literature Survey Compressive, Tensile, Bond and Shear Strength of Masonry," by Ronald L. Mayes and Ray W. Clough - 1975 (PE 246 292)Al0
- EERC 75-16 "Hysteretic Behavior of Ductile Moment Resisting Reinforced Concrete Frame Components," by V. V. Bertero and E. P. Popov - 1975 (PB 246 388)A05
- EERC 75-17 "Relationships Between Maximum Acceleration, Maximum Velocity, Distance from Source, Local Site Conditions for Moderately Strong Earthquakes," by H. Bolton Seed, Ramesh Murarka, John Lysmer and I. M. Idriss - 1975 (PB 248 172)A03
- EERC 75-18 "The Effects of Method of Sample Preparation on the Cyclic Stress-Strain Behavior of Sands," by J. Paul Mulilis, Clarence K. Chan and H. Bolton Seed - 1975
- EERC 75-19 "The Seismic Behavior of Critical Regions of Reinforced Concrete Components as Influenced by Moment, Shear and Axial Force," by B. Atalay and J. Penzien - 1975 (PB 258 842) All
- EERC 75-20 "Dynamic Properties of an Eleven Story Masonry Building," by R. M. Stephen, J. P. Hollings, J. G. Bouwkamp and D. Jurukovski - 1975 (PB 246 945)A04
- EERC 75-21 "State-of-the-Art in Seismic Shear Strength of Masonry -An Evaluation and Review," by Ronald L. Mayes and Ray W. Clough - 1975 (PB 249 040)A07
- EERC 75-22 "Frequency Dependencies Stiffness Matrices for Viscoelastic Half-Plane Foundations," by Anil K. Chopra, P. Chakrabarti and Gautam Dasgupta - 1975 (PB 248 121)A07

EERC 75-23 "Hysteretic Behavior of Reinforced Concrete Framed Walls," by T. Y. Wong, V. V. Bertero and E. P. Popov - 1975

- EERC 75-24 "Testing Facility for Subassemblages of Frame-Wall Structural Systems," by V. V. Bertero, E. P. Popov and T. Endo - 1975
- EERC 75-25 "Influence of Seismic History of the Liquefaction Characteristics of Sands," by H. Bolton Seed, Kenji Mori and Clarence K. Chan - 1975
- EERC 75-26 "The Generation and Dissipation of Pore Water Pressures during Soil Liquefaction," by H. Bolton Seed, Phillippe P. Martin and John Lysmer - 1975 (PB 252 648)A03
- EERC 75-27 "Identification of Research Needs for Improving a Seismic Design of Building Structures," by V. V. Bertero - 1975 (PB 248 136)A05
- EERC 75-28 "Evaluation of Soil Liquefaction Potential during Earthquakes," by H. Bolton Seed, I. Arango and Clarence K. Chan 1975 (NUREG 0026)A13
- EERC 75-29 "Representation of Irregular Stress Time Histories by Equivalent Uniform Stress Series in Liquefaction Analyses," by H. Bolton Seed, I. M. Idriss, F. Makdisi and N. Banerjee 1975 (PB 252 635)A03
- EERC 75-30 "FLUSH A Computer Program for Approximate 3-D Analysis of Soil-Structure Interaction Problems," by J. Lysmer, T. Udaka, C.-F. Tsai and H. B. Seed - 1975 (PB 259 332)A07
- EERC 75-31 "ALUSH A Computer Program for Seismic Response Analysis of Axisymmetric Soil-Structure Systems," by E. Berger, J. Lysmer and H. B. Seed - 1975
- EERC 75-32 "TRIP and TRAVEL Computer Programs for Soil-Structure Interaction Analysis with Horizontally Travelling Waves," by T. Udaka, J. Lysmer and H. B. Seed - 1975
- EERC 75-33 "Predicting the Performance of Structures in Regions of High Seismicity," by Joseph Penzien - 1975 (PB 248 130)A03
- EERC 75-34 "Efficient Finite Element Analysis of Seismic Structure -Soil - Direction," by J. Lysmer, H. Bolton Seed, T. Udaka, R. N. Hwang and C.-F. Tsai - 1975 (PB 253 570)A03
- EERC 75-35 "The Dynamic Behavior of a First Story Girder of a Three-Story Steel Frame Subjected to Earthquake Loading," by Ray W. Clough and Lap-Yan Li - 1975 (PB 248 841)A05
- EERC 75-36 "Earthquake Simulator Study of a Steel Frame Structure, Volume II - Analytical Results," by David T. Tang - 1975 (PB 252 926)Al0
- EERC 75-37 "ANSR-I General Purpose Computer Program for Analysis of Non-Linear Structure Response," by Digambar P. Mondkar and Graham H. Powell - 1975 (PB 252 386)A08

A-10

- EERC 75-38 "Nonlinear Response Spectra for Probabilistic Seismic Design and Damage Assessment of Reinforced Concrete Structures," by Masaya Murakami and Joseph Penzien - 1975 (PB 259 530)A05
- EERC 75-39 "Study of a Method of Feasible Directions for Optimal Elastic Design of Framed Structures Subjected to Earthquake Loading," by N. D. Walker and K. S. Pister - 1975(PB 257 781)A06
- EERC 75-40 "An Alternative Representation of the Elastic-Viscoelastic Analogy," by Gautam Dasgupta and Jerome L. Sackman - 1975 (PB 252 173)A03
- EERC 75-41 "Effect of Multi-Directional Shaking on Liquefaction of Sands," by H. Bolton Seed, Robert Pyke and Geoffrey R. Martin - 1975 (PB 258 781)A03
- EERC 76-1 "Strength and Ductility Evaluation of Existing Low-Rise Reinforced Concrete Buildings - Screening Method," by Tsuneo Okada and Boris Bresler - 1976 (PB 257 906)All
- EERC 76-2 "Experimental and Analytical Studies on the Hysteretic Behavior of Reinforced Concrete Rectangular and T-Beams," by Shao-Yeh Marshall Ma, Egor P. Popov and Vitelmo V. Bertero - 1976 (PB 257 906)All
- EERC 76-3 "Dynamic Behavior of a Multistory Triangular-Shaped Building," by J. Petrovski, R. M. Stephen, E. Gartenbaum and J. G. Bouwkamp - 1976
- EERC 76-4 "Earthquake Induced Deformations of Earth Dams," by Norman Serff and H. Bolton Seed - 1976
- EERC 76-5 "Analysis and Design of Tube-Type Tall Building Structures," by H. de Clercq and G. H. Powell - 1976 (PB 252 220)Al0
- EERC 76-6 "Time and Frequency Domain Analysis of Three-Dimensional Ground Motions, San Fernando Earthquake," by Tetsuo Kubo and Joseph Penzien - 1976 (PB 260 556)All
- EERC 76-7 "Expected Performance of Uniform Building Code Design Masonry Structures," by R. L. Mayes, Y. Omote, S. W. Chen and R. W. Clough - 1976
- EERC 76-8 "Cyclic Shear Tests on Concrete Masonry Piers, Part I -Test Results," by R. L. Mayes, Y. Omote and R. W. Clough 1976 (PB 264 424)A06
- EERC 76-9 "A Substructure Method for Earthquake Analysis of Structure -Soil Interaction," by Jorge Alberto Gutierrez and Anil K. Chopra - 1976 (PB 257 783)A08
- EERC 76-10 "Stabilization of Potentially Liquefiable Sand Deposits using Gravel Drain Systems," by H. Bolton Seed and John R. Booker - 1976 (PB 258 820)A04

- EERC 76-11 "Influence of Design and Analysis Assumptions on Computed Inelastic Response of Moderately Tall Frames," by G. H. Powell and D. G. Row - 1976
- EERC 76-12 "Sensitivity Analysis for Hysteretic Dynamic Systems: Theory and Applications," by D. Ray, K. S. Pister and E. Polak - 1976 (PB 262 859)A04
- EERC 76-13 "Coupled Lateral Torsional Response of Buildings to Ground Shaking," by Christopher L. Kan and Anil K. Chopra - 1976 (PB 257 907)A09
- EERC 76-14 "Seismic Analyses of the Banco de America," by V. V. Bertero, S. A. Mahin and J. A. Hollings - 1976
- EERC 76-15 "Reinforced Concrete Frame 2: Seismic Testing and Analytical Correlation," by Ray W. Clough and Jawahar Gidwani 1976 (PB 261 323) A08
- EERC 76-16 "Cyclic Shear Tests on Masonry Piers, Part II Analyses of Test Results," by R. L. Mayes, Y. Omote and R. W. Clough 1976
- EERC 76-17 "Structural Steel Bracing Systems: Behavior Under Cyclic Loading," by E. P. Popov, K. Takanashi and C. W. Roeder 1976 (PB 260 715) A05
- EERC 76-18 "Experimental Model Studies on Seismic Response of High Curved Overcrossings," by David Williams and William G. Godden - 1976
- EERC 76-19 "Effects of Non-Uniform Seismic Disturbances on the Dumbarton Bridge Replacement Structure," by Frank Baron and Raymond E. Hamati - 1976
- EERC 76-20 "Investigation of the Inelastic Characteristics of a Single Story Steel Structure using System Identification and Shaking Table Experiments," by Vernon C. Matzen and Hugh D. McNiven 1976 (PB 258 453) A07
- EERC 76-21 "Capacity of Columns with Splice Imperfections," by E. P. Popov, R. M. Stephen and R. Philbrick - 1976 (PB 260 378) A04
- EERC 76-22 "Response of the Olive View Hospital Main Building during the San Fernando Earthquake," by Stephen A. Mahin, Robert Collins, Anil K. Chopra and Vitelmo V. Bertero - 1976
- EERC 76-23 "A Study on the Major Factors Influencing the Strength of Masonry Prisms," by N. M. Mostaghel, R. L. Mayes, R. W. Clough and S. W. Chen - 1976
- EERC 76-24 "GADFLEA A Computer Program for the Analysis of Pore Pressure Generation and Dissipation during Cyclic or Earthquake Loading," by J. R. Booker, M. S. Rahman and H. Bolton Seed 1976 (PB 263 947)A04

- EERC 76-25 "Rehabilitation of an Existing Building: A Case Study," by B. Bresler and J. Axley - 1976
- EERC 76-26 "Correlative Investigations on Theoretical and Experimental Dynamic Behavior of a Model Bridge Structure," by Kazuhiko Kawashima and Joseph Penzien - 1976 (PB 263 388)All
- EERC 76-27 "Earthquake Response of Coupled Shear Wall Buildings," by Thirawat Srichatrapimuk - 1976 (PB 262 899)A03
- EERC 76-28 "Tensile Capacity of Partial Penetration Welds," by Egor P. Popov and Roy M. Stephen - 1976 (PB 262 899)A03
- EERC 76-29 "Analysis and Design of Numerical Integration Methods in Structural Dynamics," by Hans M. Hilber - 1976 (PB 264 410)A06
- EERC 76-30 "Contribution of a Floor System to the Dynamic Characteristics of Reinforced Concrete Buildings," by L. J. Edgar and V. V. Bertero - 1976
- EERC 76-31 "The Effects of Seismic Disturbances on the Golden Gate Bridge," by Frank Baron, Metin Arikan and Raymond E. Hamati 1976
- EERC 76-32 "Infilled Frames in Earthquake Resistant Construction," by R. E. Klinger and V. V. Bertero - 1976 (PB 265 892)A13
- UCB/EERC-77/01 "PLUSH A Computer Program for Probabilistic Finite Element Analysis of Seismic Soil-Structure Interaction," by Miguel P. Romo-Organista, John Lysmer and H. Bolton Seed - 1977
- UCB/EERC-77/02 "Soil-Structure Interaction Effects at the Humboldt Bay Power Plant in the Ferndale Earthquake of June 7, 1975," by Julio E. Valera, H. Bolton Seed, C. F. Tsai and J. Lysmer - 1977
- UCB/EERC-77/03 "Influence of Sample Disturbance on Sand Response to Cyclic Loading," by Kenji Mori, H. Bolton Seed and Clarence K. Chan - 1977 (PB 267 352)A04
- UCB/EERC-77/04 "Seismological Studies of Strong Motion Records," by J. Shoja-Taheri - 1977 (PB 269 655)A10
- UCB/EERC-77/05 "Testing Facility for Coupled-Shear Walls," by L. Li-Hyung, V. V. Bertero and E. P. Popov - 1977
- UCB/EERC-77/06 "Developing Methodologies for Evaluating the Earthquake Safety of Existing Buildings," No. 1 B. Bresler; No. 2 T. Okada and D. Zisling; No. 3 T. Okada and B. Bresler; No. 4 V. V. Bertero and B. Bresler 1977 (PB 267 354)A08
- UCB/EERC-77/07 "A Literature Survey Transverse Strength of Masonry Walls," by Y. Omote, R. L. Mayes, S. W. Chen and R. W. Clough - 1977

UCB/EERC-77/09 "SUBWALL - A Special Purpose Finite Element Computer Program for Practical Elastic Analysis and Design of Structural Walls with Substructure Option," by D. Q. Le, H. Petersson and E. P. Popov - 1977

UCB/EERC-77/10 "Experimental Evaluation of Seismic Design Methods for Broad Cylindrical Tanks," by D. P. Clough - 1977

UCB/EERC-77/11 "Earthquake Engineering at Berkeley - 1976."

UCB/EERC-77/12 "Automated Design of Earthquake Resistant Multistory Steel Building Frames," by N. D. Walker, Jr. - 1977

UCB/EERC-77/13 "Concrete Confined by Rectangular Hoops Subjected to Axial Loads," by D. Zallnas, V. V. Bertero and E. P. Popov - 1977

UCB/EERC-77/14 "Seismic Strain Induced in the Ground During Earthquakes," by Y. Sugimura - 1977

UCB/EERC-77/15 "Bond Deterioration under Generalized Loading," by V. V. Bertero, E. P. Popov and S. Viwathanatepa - 1977

UCB/EERC-77/16 "Computer Aided Optimum Design of Ductile Reinforced Concrete Moment Resisting Frames," by S. W. Zagajeski and V. V. Bertero - 1977

UCB/EERC-77/17 "Earthquake Simulation Testing of a Stepping Frame with Energy-Absorbing Devices," by J. M. Kelly and D. F. Tsztoo - 1977

UCB/EERC-77/18 "Inelastic Behavior of Eccentrically Braced Steel Frames under Cyclic Loadings," by C. W. Roeder and E. P. Popov - 1977

UCB/EERC-77/19 "A Simplified Procedure for Estimating Earthquake-Induced Deformations in Dams and Embankments," by F. I. Makdisi and H. Bolton Seed - 1977

UCB/EERC-77/20 "The Performance of Earth Dams during Earthquakes," by H. Bolton Seed, F. I. Makdisi and P. DeAlba - 1977